

Landlord Gas Safety Record

Cert. No. 12050

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure.

Company / Installer						Job Address						Customer / Landlord							
Engi	ineer Cary Derry			Name Unknown						Name Ms Sarah Esler									
Company Address Post Code		Nortons Heating Suite 4a Heritage House Osbaldwick York				Address	80					Company							
								Ambrose Street					80						
							York North Yorkshire					Post Code	Ambrose Street York						
																			TUIK
		YO19 5UW					YO10 4DR						YO10 4DR						
		Tel No.						Tel. No	Unknow	n				Tel. No	1010 4DK				
Gas Safe Reg		01904411040										Tel. NO							
ID Card No.		5771233																	
Арр	liance D	etails					Insp	ection Details	S S										
	Location	1	Appliance Type	Make	Mode	l Flu	Type Landlo	rd's Appliance Inspected		Heat Input (kW/h)	High Combustic	n Low Combustion Reading	Safety device(s)	Ventilation Provision	Visual condition of flue and	Flue Performance	Appliance Serviced	Appliance safe	
							Applia	lice	(mbar)		Ratio CO C	O2 Ratio CO CO	correct operation	satisfactory	termination satisfactory	test	Serviceu	to use	
1	Back Bedr	room	Combi Boiler	Ideal	Logic + Co	mhi C24	RS Ye	s Yes	19	22.6	ppm	% ppm % 3.5 .0005 45 8.4		Yes	Yes	Pass	Yes	Yes	
2	back bear	00111	COTTOT DOTIET	ideai	Logic i Co	IIIDI CZ4	15 16	3 103	15	22.0	.0007 01 0	.5 .0005 45 0.	103	163	163	1 033	163	163	
3																			
4																			
5																			
6																			
		1161							I ahels a	and Warning No	itica Issuad	CO. Alaway (a)	I		Outlan	al Chaale			
Dete	Defects / Identified					Labels and Warning Notice Issued				rice issueu	CO Alarm(s)								
	1	1 Condensate pipe not insulated outside			properly.			No			CO Alarm(s) fit	ted	Yes	Smoke A	Alarm(s) fitt	:ed	Yes		
	2	·			.,														
	3											CO Alarm(s) to		Pass		Alarm(s) tes	sted	Pass	
	4											and Satisfacto	ry		and Sati	isfactory			
	5														- 11				
															Water o	uality/lovel	of inhibitor		
	6														Water q accepta	uality/level ble	of inhibito	NA	
Emo	6	introl Acco	rossiblo Vos	Tinkka og Cakinfagkarı MA		Comme	nts								Water q accepta	uality/level ble	of inhibito	NA	
Eme	6	ntrol Acc	cessible Yes Gas	Tightness Satisfactory NA		Comme									Water q accepta	uality/level ble	of inhibito	NA	
	6 ergency Co		cessible Yes Gas ork Visual Inspection					not drilled or scr	ewed back to t	he wall. Replac	ed 13A fuse	for a 3A fuse in b	oiler.		Water q accepta	uality/level ble	of inhibito	NA	
Gas	6 ergency Co	n Pipewo	ork Visual Inspection					not drilled or scr	ewed back to t	he wall. Replac	ed 13A fuse 1	for a 3A fuse in b	oiler.		Water q accepta	uality/level ble	of inhibito	NA	
Gas E	6 ergency Col Installation Equipotenti	n Pipewo ial Bondi	ork Visual Inspection					not drilled or scr	ewed back to t	he wall. Replac	ed 13A fuse	for a 3A fuse in b	oiler.		Water q accepta	uality/level ble	of inhibito	NA NA	
Gas E	6 ergency Col Installation Equipotenti	n Pipewo ial Bondi	ork Visual Inspection	Satisfactory Yes				not drilled or scr	ewed back to t	he wall. Replac	ed 13A fuse	for a 3A fuse in b	oiler.		Water q accepta	uality/level ble	of inhibito	NA NA	
Gas E	6 ergency Col Installation Equipotenti	n Pipewo ial Bondi	ork Visual Inspection	Satisfactory Yes				not drilled or scr	ewed back to t	he wall. Replac	ed 13A fuse	for a 3A fuse in b	oiler.		Water q accepta	uality/level ble	of inhibito	NA NA	
Gas E	6 ergency Col Installation Equipotenti	n Pipewo ial Bondi	ork Visual Inspection	Satisfactory Yes				not drilled or scr	ewed back to t	he wall. Replac	ed 13A fuse	for a 3A fuse in b	oiler.		Water q accepta	uality/level ble	of inhibito	NA	
Gas E NEX	6 ergency Col Installation Equipotenti	n Pipewo ial Bondi	ork Visual Inspection	Satisfactory Yes				not drilled or scr	ewed back to t	he wall. Replac	ed 13A fuse	for a 3A fuse in b	oiler.		Water q accepta	uality/level ble	of inhibito	NA	
Gas E NEX	6 ergency Col Installation Equipotenti	n Pipewo ial Bondi	ork Visual Inspection ing Yes UE BEFORE	Satisfactory Yes			Co detecto	not drilled or scr	ewed back to t	he wall. Replac	ed 13A fuse	for a 3A fuse in b		ov-2024	Water q accepta	uality/level ble	of inhibito	NA	
Gas E NEX	ergency Col Installation Equipotenti KT INSPEC	n Pipewo	ork Visual Inspection ing Yes UE BEFORE	Satisfactory Yes	R	Smoke/0	Co detecto	not drilled or scr	ewed back to t	he wall. Replac	ed 13A fuse			ov-2024	Water q accepta	uality/level ble	of inhibito	NA	
Gas E NEX	ergency Col Installation Equipotenti KT INSPEC	n Pipewo	ork Visual Inspection ing Yes UE BEFORE	Satisfactory Yes	R	Smoke/0	Co detecto	not drilled or scr	ewed back to t	he wall. Replac	ed 13A fuse			ov-2024	Water q accepta	uality/level ble	of inhibito	NA	