



This certificate is not valid if the serial number has been defaced or altered

29152702

EICR18.2c

ELECTRICAL INSTALLATION CONDITION REPORT

PART 1: DETAILS OF THE CONTRACTOR, CLIENT AND	O INSTALLATION								
DETAILS OF THE CONTRACTOR Registration No: 501766000 Branch No*: 000 Trading Title: Advanced Electrical Services York Ltd Address: York Eco Business Centre, York Amy Johnson Way, York, North Yorkshire Postcode: YO30 4AG Tel No: 01904479485	DETAILS OF THE CLIENT Contractor Reference Number (CRN): N/A Name: Adam Bennett Address 58 Gillygate, YORK Postcode: YO31 7EQ Tel No: N/A		DETAILS OF THE INSTALLATION Occupier: Unknown UPRN: N/A Address: Flat D, 136 Lawrence Street, York, North Yorkshire Postcode: YO10 3EB Tel No: N/A						
PART 2 : PURPOSE OF THE REPORT									
Purpose for which this report is required: Scheduled report prior to property being rented to comply with the Electric Date(s) when inspection and testing was carried out: (06/03/2024)	etrical safety standard in the private rental s	sector (England) regulations as a		Previous report date: (N/A)					
PART 3: SUMMARY OF THE CONDITION OF THE INST	ALLATION								
General condition of the installation (in terms of electrical safety): The installation appears to be in acceptable condition with regards to electrical safety. Accessories in good condition. Installation erected to previous version of BS7671 Description of premises Dwelling: (
PART 4: DECLARATION									
INSPECTION AND TESTING I/We, being the person responsible for the inspection and testing of the electrical installation declare that the information in this report, including the observations (PART 5) and the attache Name (capitals) on behalf of the contractor identified in PART 1: OLLIE WALKER I/We further RECOMMEND, subject to the necessary remedial action being taken, that the ins Give reason for recommendation: Domestic rental property The proposed date for the next inspection should take into consideration any legislative or licensing require REVIEWED BY THE REGISTERED QUALIFIED SUPERVISOR FOR THE CONT	ed Schedules, provides an accurate assessment of the consideration is inspected and tested by:06/03/2029	ondition of the electrical installation taking gnature:	into account the stated extent a	and limitations in PART 6 of this report. Date: 06/03/2024					
Name (capitals) on behalf of the contractor identified in PART1: MATTHEW CHIPCH		gnature:		Date:26/03/2024					

APPROVED CONTRACTOR This certificate is not valid if the serial number has been defaced or altered

29152702

EICR18.2c

ELECTRICAL INSTALLATION CONDITION REPORT

PART 5 : OBSERVATIONS						
One of the following Codes, as appropriate, has b below to indicate to the person(s) responsible for for remedial action:	Code C3 Improvement Recommended	Further	Code FI Further Investigation Required			
Referring to the Schedule of Items Inspected (see PA	RT 9), the attached Schedule of Circuit Details and Te s	st Results (see PART 11A & 11B), and subject t	o any agreed limitations listed in PART 6	-		
No remedial action is required (.X), OR Th	e following observations are made:					
Item No		Observation(s)			Code	Location Reference
	ed from flammable materials and located in				()	()
	consumer unit are type AC (possible DC lo			,	(.C3)	(Consumer unit
	ne circuits concealed less than 50mm deep				(.C3)	(Final circuits)
(.4) (Absence of Surge Protecti	ive Device (SPD) where required by 443.4.	1 i-iii)	(.C3)	(Installation)
())	()	()
())	()	()
())	()	()
())	()	()
())	()	()
())	()	()
())	()	()
())	()	()
())	()	()
())	()	()
())	()	()
())	()	()
())	()	()
())	()	()
())	()	()
())	()	()
			Ado	ditional pages? () State	e page number	s: (N/A
Immediate remedial action required for items:	(N/A	Improve	ement recommended for items:	(.1,2,3,4		
Urgent remedial action required for items:	(N/A) Further	investigation required for items:	(.N/A		





Issued in accordance with BS 7671: 2018+A2:2022 - Requirements for Electrical Installations

PART 6: DETAILS AND LIMITATI	ONS OF THE INSPECTION AND	TESTING									
	nspected unless specifically agreed between the Client	and the Inspector prior to inspection.		s and conduits concealed under floors, in inaccessible ro	. ,						
					,						
Agreed limitations including the reasons, if any, on the undertaken in any building voids/loft space	a and continuation about for more	nsulation resistance tests carried out		age to connected equipment. No test or insp	ection has been						
				Agreed with (print name): CLIENT							
Extent of sampling: A minimum of 20% of acc	cessories have been visually checked for co	ompliance			(see additional page No.N/A)						
Operational limitations including the reasons: Unab	le to determine size and type of main suppl	y company fuse as unit is sealed and	d access forbidd	en	(see additional page No.N/A)						
PART 7 : SUPPLY CHARACTERIS	TICS AND EARTHING ARRANGE	MENTS									
$\begin{tabular}{lll} \textbf{System type and earthing arrangements} \\ \hline TN-C: (N/A &) & TN-S: (N/A &) \\ \hline TT: (N/A &) & IT: (N/A &) \\ \hline \textbf{Supply protective device} \\ \hline BS EN: (Non-verifiable &) & Type: (N/A &) \\ \hline \end{tabular}$	TN-C-S: (*) AC 1-phase, 2- 3-phase, 3 DC 2-wire: (N/A Rated current: (N/A) A Other sources of	(N/A) V [2] By enquiry (230) V (50) Hz (1.96) kA (012) Ω									
PART 8 : PARTICULARS OF INST	ALLATION REFERRED TO IN THI	S REPORT									
Maximum demand (load): (45) XXX/A	Main protective conductors	Main protective bonding connections	Main sw	tch / Switch-fuse / Circuit-breaker / RCD							
(delete as appropriate)	Earthing conductor:	Water installation pipes: (.) Location:	(Within consumer unit)						
Means of Earthing	(material Copper)	Gas installation pipes: (.	.) BS EN:	(60947-3) Type: (3)	Rating / setting of device: (N/A) A						
Distributor's facility: ()	csa (16) mm ² Connection/continuity	The state of the s	, , ,, ,, ,								
Installation earth electrode(s): (N/A)	verified: (🖋)		N/A)								
Earth electrode type – rod(s), tape, etc: (None)	Main protective bonding conductors:		N/A Where a	n RCD is used as the main switch							
Location: (N/A)	(material Copper)	Other (state):	RCD rated	I residual operating current, $I_{\Delta n}$: (N/A) mA	RCD Type: (N/A)						
Electrode resistance to Earth: $(N/A) \Omega$	csa (10) mm ² Connection/continuity verified: (🖊) N/A (N/A) Rated time delay: (N/A) ms Measured operating time: (N/A)										

All fields must be completed. Enter either, as appropriate: '

' if Acceptable condition; 'N/A' if Not applicable; 'LIM' if a Limitation exists, or Code appropriately: CODE 'C1,' C2,' C3' or 'FI' (codes to be recorded in PART 5, with additional comments (where appropriate) on attached numbered sheets)

^{*}Where the installation is supplied by more than one source, the higher or highest values of prospective fault current, Ipf, and external earth fault loop impedance, Ze, must be recorded.





This certificate is not valid if the serial

number has been defaced or altered

Issued in accordance with BS 7671: 2018+A2:2022 - Requirements for Electrical Installations

PART 9: SCHEDULE OF ITEMS INSPECTED (enter /, N/A or Classification Code C1, C2, C3 or FL as applicable)

PART 9 : SCHEDULE OF ITEMS INSPECTED (enter	er ✓, N/A	or Classification Code C1, C2, C3 or FI, as applicable)	
1.0 Intake equipment (visual inspection only)	1	Accessibility of all protective bonding connections (543.3.2) (
An outcome against an item in section 1.1, other than access to live parts, should not be u	used to	Provision of earthing / bonding labels at all appropriate locations (514.13.1) ((N/A)
determine the overall assessment of the installation. Where inadequacies are identified, should be put against the appropriate item and a comment made in Part 5 of this report.		3.2 FELV - requirements satisfied (411.7) (N/A 1.7 Presence of diagrams, charts or schedules at or near equipment, where required (514.9.1)	(•
1.1 Distributor / supplier intake equipment		3.3 Other methods of protection 4.18 Presence of alternative supply warning notice at or near equipment,	
Service cable	()	Where any of the methods listed below are employed, details should be provided on separate sheets where required (514.15)	(N/A ()
Service head	(•	• Non-conducting location (418.1) (N/A 4.19 Presence of next inspection recommendation label,	
Earthing arrangement	(.⁄)	Earth-free local equipotential bonding (418.2) (N/A) where required (514.12.1)	()
Meter tails	()	• Electrical separation (413; 418.3) (N/A 4.20 Presence of other required labelling (please specify) (514)	(N/A)
Metering equipment	(•	• Double insulation (412) (N/A) 4.21 Compatibility of protective devices, bases and other components;	
 Isolator, where present 	(•	Reinforced insulation (412) (N/A) correct type and rating (no signs of unacceptable thermal damage, arcing or overheating) (432; 433; 434)	(.
Where inadequacies in the intake equipment are encountered, which may result in a dangerous		 Provisions where automatic disconnection of supply is not feasible (419) (N/A) 4.22 Single-pole switching or protective devices in line conductors only 	()
potentially dangerous situation, the person ordering the work and / or dutyholder must be info		4.22 Single-pole switching or protective devices in line conductors only (132.14.1; 530.3.3)	(.⁄)
It is strongly recommended that the person ordering the work informs the appropriate authority	·	A.1 Adequacy of working space / accessibility to equipment (132.12; 513.1) (, ,
	(N/A ()	4.2 Security of fixing (134.1.1) ((.)
1.3 Consumer's meter tails	()	4.3 Condition of insulation of live parts (416.1) (
2.0 Presence of adequate arrangements for parallel or switched alternative	sources	4.4 Adequacy security of barriers or enclosures (416.2.3) ((•
2.1 Adequate arrangements where a generating set operates as a switched	NI/A	4.5 Condition of enclosure(s) in terms of IP rating, etc. (416.2) (
	(N/A)	4.6 Condition of enclosure(s) in terms of fire rating, etc. (421.1.201; 421.1.6; 526.5) (C3)	(N/A ()
2.2 Adequate arrangements where a generating set operates in parallel	(N/A ()	1.7 Enclosure not damaged / deteriorated so as to impair safety (651.2) ((N/A)
	()	4.8 Presence and effectiveness of obstacles (417.2) ((N/A)
3.0 Methods of protection		Presence of main switch(es), linked where required (462.1; 462.1.201; 462.2) (
3.1 Automatic disconnection of supply (ADS)	,	4.10 Operation of main switch(es) (functional check) (643.10) (trunking (521.10.1)	(N/A)
	()	1.11 Manual operation of circuit-breakers, RCDs and AFDDs to prove 5.5 Suitability of containment systems for continued use	N 1/A
Presence of distributor's earthing arrangement (542.1.2.1; 542.1.2.2), or presence of installation parth plantages arrangement (541.1.2.3).	()	functionality (643.10) (including flexible conduit) (522)	(N/A ()
	(·)	4.12 Confirmation that integral test button / switch causes RCD(s) to trip 5.6 Cables correctly terminated in enclosures (526)	(N/A)
Adequacy of earthing conductor size (542.3; 543.1.1) Adequacy of earthing conductor connections (543.3.2)	(·)	when operated (functional check) (643.10) (Ν/Δ .
	(.)	RCD(s) provided for fault protection - includes RCBOs busbars, are correctly located in terminals and are tight and secure (526.1) (411.4.204; 411.4.5; 411.5.2; 531.2) (N/A) (N/A) (N/A) (N/A) (N/A)) (N/A)
	(.)	(411.4.204; 411.4.5; 411.5.2; 531.2) 5.8 Examination of cables for signs of unacceptable thermal or mechanical damage / deterioration (421.1; 522.6)	(N/A)
	(.)	includes RCBOs (411.3.3; 415.1) (C3) 5.9 Adequacy of cables for current-carrying capacity with regard for the type	
 Adequacy and location of main protective bonding conductor connections (544.1.2) 	(·)	4.15 Presence of RCD six-monthly test notice, where required (514.12.2) ()	(N/A ()
· · · · · · · · · · · · · · · · · · ·	()		. ,





This certificate is not valid if the serial

number has been defaced or altered





This certificate is not valid if the serial number has been defaced or altered

29152702

EICR18.2c

ELECTRICAL INSTALLATION CONDITION REPORT

None

Page No(s):

Issued in accordance with BS 7671: 2018+A2:2022 - Requirements for Electrical Installations

PA	RT 9 : SCHEDULE OF ITE	EMS INSPECTED (enter √, N	/A oı	r Classification Code C1, C2, C3	or FI, as applicable)						
7.2	Switching off for mechanical maintenan		8.5	Security of fixing (134.1.1)		(Low voltage (e.g. 230 volt) socket-outlets sited at least 2.5 m from zone 1 (701.512.3) 	Ţ			
	Presence and condition of appropriate of Capable of being secured in the OFF post continuous supervision (464.2)			Cable entry holes in ceiling above lumin restrict the spread of fire: list number a inspected (separate page) (527.2)	nd location of luminaires	()	zone 1 (701.512.3) • Suitability of equipment for external influences for installed location in terms of IP rating (701.512.2) (, ,			
7.3	Correct operation verified (643.10) Clearly identified by position and / or du Emergency switching off – Presence and condition of appropriate of Readily accessible for operation where of Correct operation verified (643.10) Clearly identified by position and / or du (537.3.3.5; 537.3.3.6; 537.4.3; 537.4.4) Functional switching – Presence and condition of appropriate of	rable marking (537.3.2.4) devices (465; 537.3.3; 537.4) danger might occur (537.3.3.6) N/A N/A N/A N/A N/A	8.7 9.0 9.0 Who	Recessed luminaires (downlighters) – Correct type of lamps fitted (559.3.1) Installed to minimise build-up of heat be insulation displacement box or similar (No signs of overheating to surrounding No signs of overheating to conductors of the second locations and installations are special installations or locations relating to a predule(s) should be provided on separate pages. Location(s) containing a bath or showe	y use of "fire rated" fittings, (421.1.2) (building fabric (559.4.1) (/ terminations (526.1) (particular Section of Part 7, an additional In	(N/A ()	Suitability of accessories and controlgear etc. for a particular zone (701.512.3) Suitability of current-using equipment for particular position within the location (701.55) 9.2 Other special installations or locations – N/A N/A (N/A (,)))			
•	Correct operation verified (643.10) Current-using equipment (permanent Condition of equipment in terms of IP ra	tly connected)	-	 Additional protection by RCD having rat exceeding 30 mA for all low voltage (LV passing through zones 1 and / or 2 of th Where used as a protective measure, re 	circuits serving the location or le location (701.411.3.3) (()	10.0 Prosumer's low voltage installation (N./A. Where elements of a prosuming installation falling within the scope of Chapter 82 are covered by the report, additional schedules detailing the associated inspection and testing should be provided on separate pages.)			
8.2 8.3 8.4	(416.2; 422.3; 422.4; 522.4) Equipment does not constitute a fire haze Enclosure not damaged / deteriorated s (134.1.1; 416.2) Suitability for the environment and external	zard (421) () .	met (701.414.4.5) Shaver supply units complying with <i>BS</i> (701.512.3) Presence of supplementary bonding co by <i>BS 7671: 2018</i> (701.415.2)	EN 61558-2-5 formerly BS 3535 (Inductors, unless not required	() () (N/A	Schedule of Items Inspected by Name (capitals): OLLIE WALKER Signature: Date: 06/03/2024				
PA	PART 10 : SCHEDULES AND ADDITIONAL PAGES (the pages identified are an essential part of this report (see Regulation 653.2))										
Sch	edule of Inspections	Schedule of Circuit Details and Test		ditional pages, including data sheets	Special installations or locations		Schedules relating to Prosumer's Continuation sheets				

Page No(s):

None

Page No(s):

7 & 8

Page No(s):

4,5 & 6

Page No(s):

None

Page No(s):





This certificate is not valid if the serial

number has been defaced or altered

PA	PART 11A: SCHEDULE OF CIRCUIT DETAILS (GO TO Part 11B 'Schedule of Test Results' to enter test results for the corresponding circuit listed in this part)															
_	Circuit description		po	erved		Circuit conductor (number & csa)		Overcurrent protective device					RCD			
Circuit number			Reference Method (BS7671)	Number of points served	Live (mm²)	cpc (mm²)	Max. disconnection time (BS 7671)	BS (EN)	Туре	Rating (A)	Short- circuit capacity (kA)	Maximum permitted Zs*	BS (EN)	Туре	Rating (A)	Operating current, I _{An} (mA)
1	Spare	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	Smoke alarms	Α	С	2	1.5	1	0.4	60898	В	6	6	7.28	N/A	N/A	N/A	N/A
3	Boiler	Α	С	1	1.5	1	0.4	60898	В	6	6	7.28	N/A	N/A	N/A	N/A
4	Alarm	Α	С	1	1	1	0.4	60898	В	6	6	7.28	N/A	N/A	N/A	N/A
5	Spare	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6	Spare	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
7	Lighting	A	101	7	1.5	1	0.4	60898	В	6	6	7.28	N/A	N/A	N/A	N/A
8	House sockets	Α	С	8	2.5	1.5	0.4	60898	В	20	6	2.19	N/A	N/A	N/A	N/A
9	Kitchen sockets	A	С	4	2.5	1.5	0.4	60898	В	32	6	1.37	N/A	N/A	N/A	N/A
10	Cooker	Α	С	1	6	2.5	0.4	60898	В	32	6	1.37	N/A	N/A	N/A	N/A
	RCD	N/A	N/A	N/A	N/A	N/A	0.4	N/A	N/A	N/A	N/A	N/A	61008	AC	63	30
	RCD	N/A	N/A	N/A	N/A	N/A	0.4	N/A	N/A	N/A	N/A	N/A	61008	AC	63	30
<u> </u>			*****													
DBo	DISTRIBUTION BOARD (DB) DETAILS (complete in every case) DB designation: DB-01 **SPD Type. Where combined T1 + T2 or T2 + T3 device is installed, indicate by ticking both							TO BE COMPLETED ONLY IF THE DB IS NOT CONNECTED DIRECTLY TO THE ORIGIN OF THE INSTALLATION Supply to DB is from: N/A								
Loca	ation of DB: Hall Z_{db} : 0.12 I_{pf} at DB+;1.96			devices ar	re installed o		Overcurrent protective device for the distribution circuit									
Con	firmation of supply polarity: () Phase sequence confirmed†:	(N/A ()			equipment, o s' (PART 11B		BS (EN): (N/A) Type: (N/A) Nominal voltage: (N/A) V Rating: (N/A) A No. of phases: (N/A)									
SPD	Details** Types: T1 (N/A) T2 (N/A) T3 (N/A) N/A	(N/A	(See Sect	ion 534 for	further deta	ails).		ed RCD (if any)								
	us indicator checked (where functionality indicator is present):	BS (EN): (N/A) RCD Type: (N/A) $I_{\Delta n}$: (N/A) mA No. of poles: (N/A) Operating time: (N/A) ms														





Issued in accordance with BS 7671: 2018+A2:2022 - Requirements for Electrical Installations

PA	PART 11B : SCHEDULE OF TEST RESULTS (MUST reflect circuits entered into 'Schedule of Circuit Details' in Part 11A)													
	Continuity (Ω)						Insulation resistance			ired loop s,Zs	RCD RCD		AFDD**	
Circuit number		ng final circuits easured end to		(complete	ircuits at least one umn)	Live / Live	Live / Earth	Test voltage DC	Polarity	Max. measu earth fault impedance	Max. measured with the door and the three services of the serv		AFDD test button	Comments and additional information, where required
	(Line) r ₁	(Neutral) r _n	(cpc) r ₂	(R ₁ + R ₂)	R ₂	(ΜΩ)	(MΩ)	(V)	(1)	(Ω)	(ms)	(✓)	(✓)	
1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	N/A	N/A	N/A	0.37	N/A	LIM	100	500	V	0.49	N/A	N/A	N/A	N/A
3	N/A	N/A	N/A	0.22	N/A	LIM	100	500	1	0.34	N/A	N/A	N/A	N/A
4	N/A	N/A	N/A	0.05	N/A	LIM	100	500	1	0.17	N/A	N/A	N/A	N/A
5	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
7	N/A	N/A	N/A	0.38	N/A	LIM	40	500	~	0.50	N/A	N/A	N/A	N/A
	N/A	N/A	N/A	0.56	N/A			500		0.66		N/A	N/A	Circuit was a ring, faulty leg disconnected and 20a mcb installed
			0.44	0.23	N/A	LIM		500	_	0.54		N/A	N/A	N/A
	N/A		N/A	0.17	N/A	LIM		500						N/A
	N/A	N/A	N/A	N/A		1		N/A		1	25.1			N/A
	N/A	N/A	N/A	N/A	1	1		N/A		1	25.1		N/A	N/A
		1411												
Circ	Circuits/equipment vulnerable to damage when testing (where applicable): N/A													
TE	STED BY	Name (capitals): O	LLIE WAL	KER				Positio	n: Electric	ian			Signature:
TE	ST INSTR	UMENTS (ENTER SE	RIAL NUM	BER AGAI	NST EACH	INSTRUM	MENT USE	D)					
Mul	ti-function:			Conti	nuity:			Insulatio	on resist	ance:		Ear	th fault loo	op impedance: Earth electrode resistance: RCD:
10	1598367			N/A				N/A				. <u>N</u> /.	Α	N/A N/A
RCD	effectiven	ess is verifi	ed using a	n alternating	current te	st at rated r	esidual ope	erating curre	ent (I _{An})		** Where	installed	. Note, no	ot all AFDDs have a test function. Where a circuit contains an AFDD this should be stated in the field for that

@ Copyright Certsure LLP (May 2023)

(F)

Thermoplastic cables in non-metallic trunking

Thermoplastic cables in metallic trunking

(D)

circuit in the 'Comments and additional information, where required' column.

Thermoplastic / SWA cables (G) Thermosetting / SWA cables

Other (state):N/A

(H) Mineral-insulated cables





This certificate is not valid if the serial number has been defaced or altered

29152702

N18.2c

GENERAL CONTINUATION SHEET

Issued in accordance with BS 7671: 2018+A2:2022 - Requirements for Electrical Installations

NOTES

Agreed limitations

Accessories such as sockets and light switches not unscrewed where decor may be damaged.

Fixed equipment such as cookers, or other hard wired equipment tested at point of isolation.

Socket-outlets or connection points behind washing-machines, dishwashers, cooker-hoods etc not inspected or tested.

Only wiring that can be reasonably accessed has been visually inspected.

Circuits incorporating integrated appliances only tested at isolation spur unit and not at socket outlet behind appliance to prevent damage to goods and floor areas where moving would be required.

Central heating system including wiring to thermostats and control / wiring centres not inspected - tested to isolation point only.

Zs values may be calculated to prevent access to exposed live parts during testing

Unable to determine whether cables are routed in prescribed cable zones due to building fabric (plaster etc)

Page 9

NOTES FOR RECIPIENT

THIS CONDITION REPORT IS AN IMPORTANT AND VALUABLE DOCUMENT WHICH SHOULD BE RETAINED FOR FUTURE USE

The purpose of periodic inspection is to determine, so far as is reasonably practicable, whether an electrical installation is in a satisfactory condition for continued service. This report provides an assessment of the condition of the electrical installation identified overleaf at the time it was inspected and tested, taking into account the stated extent of the installation and the limitations of the inspection and testing.

This report has been issued in accordance with the national standard for the safety of electrical installations, BS 7671: 2018+A2:2022 – Requirements for Electrical Installations.

The report identifies any damage, deterioration, defects and/or conditions found by the inspector which may give rise to danger (see PART 5), together with any items for which improvement is recommended.

You should have received the report marked 'Original' and the contractor should retain a duplicate. If you were the person ordering this report, but not the owner or user of the installation, you should pass this report, or a full copy of it, including these notes, the schedules and additional pages (if any), immediately to the owner or user of the installation.

This report should be retained in a safe place and shown to any person inspecting or undertaking further work on the electrical installation in the future. If you later vacate the property, this report will provide the new user with an assessment of the condition of the electrical installation at the time the periodic inspection was carried out.

For safety reasons, the electrical installation should be re-inspected at appropriate intervals by a skilled person or persons, competent in such work. NICEIC* recommends that you engage the services of an NICEIC contractor for the inspection. Only an NICEIC contractor is authorised to issue this NICEIC Electrical Installation Condition Report, which has a unique serial number that is traceable to the contractor to which it was supplied by NICEIC.

The recommended date by which the next inspection should be carried out is stated in PART 4 of this report. With the exception of domestic (household) premises, there should also be a notice at or near the main switchboard or distribution board/consumer unit indicating when the next inspection of the installation is due.

This report is intended to be issued only for the purpose of reporting on the condition of an existing electrical installation and must not be issued to certify new electrical installation work including the replacement of a distribution board or consumer unit.

The report consists of at least eight numbered pages. The report is only valid if the Schedule of Items Inspected (PART 9) has been completed to confirm that all relevant inspections have been carried out and the Schedule of Circuit Details (PART 11A) and the Schedule of Test Results (PART 11B) are attached. For installations having more than one distribution board (or consumer unit) or more circuits than can be recorded in PARTS 11A & 11B, one or more additional Schedule of Circuit Details and Schedule of Test Results, should form part of the report. Additional numbered pages may have been provided to permit further relevant information relating to the installation to be recorded. The report is invalid if any of the additional pages, listed in PART 10 are missing.

Where the installation includes a residual current device (RCD) it should be tested every six months by pressing the button marked "T" or "Test". The device should switch off the supply and should then be switched on to restore the supply. If the device does not switch off the supply when the button is pressed, seek expert advice. For safety reasons it is important that this instruction is followed.

Where the installation includes an arc fault detection device (AFDD) having a manual test facility it should be tested six-monthly by pressing the test button. Where an AFDD has both a test button and automatic test function, manufacturer's instructions should be followed with respect to test button operation.

Where the installation includes a surge protection device (SPD) the status indicator should be checked to confirm it is in operational condition in accordance with manufacturer's information. If the indication shows that the device is not operational, seek expert advice.

Where the installation can be supplied by more than one source, such as the public supply and a standby generator or microgenerator, this should be identified in PART 7 Supply Characteristics and Earthing Arrangements, and the Schedules of Circuit Details and Test Results (PART 11A & 11B) compiled accordingly.

PART 6 (Details and limitations) should identify fully the extent of the installation covered by this report and any limitations on the inspection and testing. The inspector should have agreed these aspects with the person ordering the report and with other interested parties (licensing authority, insurance company, mortgage provider and the like) before the inspection was carried out.

Operational limitations may have been encountered during the inspection such as inability to gain access to parts of the installation or to an item of equipment. The inspector should have noted any such limitations in PART 6. It should be noted that the greater the limitations applying to a report, the less its value from the safety aspect.

A declaration should have been given by the inspector in PART 4 of the report. The declaration must reflect the statement given in PART 3, which summarises the observations and recommendations made in PART 5. Where one or more observations have been made in PART 5, the Classification code given to each by the inspector indicates the degree of urgency with which remedial action needs to be taken to restore the installation to a safe working condition.

Where the inspector has indicated an observation as code C1 (danger present) the safety of those using the installation is at risk. Wherever practicable, items classified as C1 should be made safe on discovery, and it is recommended that a skilled person(s) competent in electrical installation work undertakes the necessary remedial work immediately.

Where the inspector has indicated an observation as code C2 (potentially dangerous) the safety of those using the installation may be at risk, and it is recommended that a skilled person competent in electrical installation work undertakes the necessary remedial work as a matter of urgency.

Where the inspector has indicated that an item requires further investigation (FI), the investigation should be carried out without delay to determine whether danger or potential danger exists. For further guidance on the Classification codes, please see the reverse of page 2.

Where inadequacies in the intake equipment have been observed (Item 1 of PART 9), the person ordering the inspection should inform the distributor and/or supplier as appropriate.

Should the person ordering this report have reason to believe that it does not reasonably reflect the condition of the electrical installation reported on, that person should in the first instance raise the specific concerns in writing with the contractor. If the concerns remain unresolved, the person ordering this report may make a formal complaint to NICEIC, for which purpose a complaint form is available on request.

The complaints procedure offered by NICEIC is subject to certain terms and conditions, full details of which are available upon application. NICEIC does not investigate complaints relating to the operational performance of electrical installations (such as lighting levels), or to contractual or commercial issues (such as time or cost).

For further information about electrical safety and how NICEIC can help you, visit:

www.niceic.com

* NICEIC is operated by Certsure LLP, a partnership between the Electrical Contractors' Association and the charity, Electrical Safety First. NICEIC maintains and publishes registers of electrical contractors that it has assessed against particular scheme requirements (including the technical standard of electrical work).

GUIDANCE FOR RECIPIENTS ON THE CLASSIFICATION CODES ONLY ONE CLASSIFICATION CODE SHOULD BE GIVEN FOR EACH RECORDED OBSERVATION

Classification code C1 (Danger present)

Where an observation has been given a Classification code C1, the safety of those using the installation is at risk and immediate remedial action is required.

The person responsible for the maintenance of the installation is advised to take action without delay to remedy the observed deficiency in the installation, or to take other appropriate action (such as switching off and isolating the affected part(s) of the installation) to remove the danger. The NICEIC contractor issuing this report will be able to provide further advice.

NICEIC makes available 'Electrical Danger Notification' forms to enable inspectors to record, and then to communicate to the person ordering the report, any dangerous condition discovered.

Classification code C2 (Potentially dangerous)

Classification code C2 indicates that, whilst those using the installation may not be at immediate risk, urgent remedial action is required to remove potential danger. The NICEIC contractor issuing this report will be able to provide further advice.

It is important to note that the recommendation given for the next inspection date in PART 4 of this report is conditional upon all items which have been given a Classification code C1 and code C2 being remedied immediately and as a matter of urgency, respectively.

It would not be reasonable for the inspector to indicate that the installation is in a satisfactory condition if any observation in this report has been given a code C1 or code C2 classification.

Classification code C3 (Improvement recommended)

Where an observation has been given a Classification code C3, the inspection and/or testing has revealed a non-compliance with the current safety standard which, whilst not presenting immediate or potential danger, would result in a significant safety improvement if remedied. Careful consideration should be given to the safety benefits of improving these aspects of the installation. The NICEIC contractor issuing this report will be able to provide further advice.

Code FI (Further investigation required without delay)

It should usually be possible for the inspector to attribute a Classification code to each observation without indicating a need for further investigation.

However, where 'FI' has been entered against an observation the inspector considers that further investigation of that observation is likely to reveal danger or potential danger that, due to the agreed extent or limitations of the inspection and/or testing (entered in PART 6), could not be fully identified at the time.

It would not be appropriate for the inspector to indicate that the installation is in a satisfactory condition if there is reasonable doubt as to whether danger or potential danger exists. Consequently, where the inspector has indicated 'Further investigation required without delay' (FI) the overall assessment of the installation (PART 3) should be marked as 'Unsatisfactory'.

If the inspector has indicated that an observation requires further investigation without delay, the person ordering this report is advised to arrange for the NICEIC contractor issuing the report (or another skilled person or persons competent in such work) to undertake further examination of that aspect of the installation as a matter of urgency, to determine whether or not danger or potential danger exists.

Further information

Further information on the application of Classification codes, primarily aimed at inspectors but of possible interest to persons ordering condition reports, can be found in Electrical Safety First's Best Practice Guide No 4 *Electrical installation condition reporting: Classification Codes for domestic and similar electrical installations*. The guide can be viewed or downloaded free of charge from www.electricalsafetyfirst.org.uk

For further information about electrical safety and how NICEIC can help you, visit www.niceic.com