

EICR18.3C

# **ELECTRICAL INSTALLATION CONDITION REPORT**

PART 1 : DETAILS OF THE CONTRACTOR, CLIENT ANI	DINSTALLATION	
DETAILS OF THE CONTRACTOR       (*Where applicable)         Registration Nº:       501766000         Branch Nº*:       000         Trading Title:       Advanced Electrical Services York Ltd         Address:       York Eco Business Centre, York Amy Johnson         Way, York, North Yorkshire	DETAILS OF THE CLIENT Contractor Reference Number (CRN): N/A Name: Adam Bennett Address 58 Gillygate, YORK	DETAILS OF THE INSTALLATION Occupier: Unknown UPRN: N/A Address: 13 Earle Street, York, North Yorkshire
Postcode: YO30 4AG Tel No: 01904479485	Postcode: YO31 7EQ Tel No: N/A	Postcode: YO31 8LJ Tel No: N/A
PART 2 : PURPOSE OF THE REPORT		
Purpose for which this report is required: Scheduled report prior to property being rented to comply with the Elec	ctrical safety standard in the private rental sector (England) regula	ations as amended
Date(s) when inspection and testing was carried out: (	Records available (651.1): (	ort available (651.1): (
PART 3 : SUMMARY OF THE CONDITION OF THE INST	TALLATION	
General condition of the installation (in terms of electrical safety):The installation app BS7671	pears to be in acceptable condition with regards to electrical safe	ty. Accessories in good condition. Installation erected to previous version of
Description of premises Dwelling: () Commercial: () Indu	ustrial: (N/A	
Estimated age of electrical installation: (30) years Evidence of additions or alterat **An unsatisfactory assessment indicates that dangerous (Code C1) and/or potenti		stallation for continued use: <b>Satisfactory /WASSTATEOTORY</b> ** (delete as appropriate) of this report) and it is recommended that these are acted upon as a matter of urgency.
PART 4 : DECLARATION		
INSPECTION AND TESTING		
I/We, being the person responsible for the inspection and testing of the electrical installation declare that the information in this report, including the observations (PART 5) and the attache Name (capitals) on behalf of the contractor identified in PART 1: THOMAS BURDETT	ed Schedules, provides an accurate assessment of the condition of the electrical insta	6, having exercised reasonable skill and care when carrying out the inspection and testing, hereby llation taking into account the stated extent and limitations in PART 6 of this report. Date: 08/05/2025
I/We further RECOMMEND, subject to the necessary remedial action being taken, that the ins Give reason for recommendation:	tallation is inspected and tested by:08/05/2030 (date)	
The proposed date for the next inspection should take into consideration any legislative or licensing require	ements and the frequency and quality of maintenance that the installation can reasonably be expe	sted to receive during its intended life. The period should be agreed between relevant parties.
REVIEWED BY THE REGISTERED QUALIFIED SUPERVISOR FOR THE CONT		k
Name (capitals) on behalf of the contractor identified in PART 1 :MATTHEW CHIPCH	ASE Signature:	Date:
This report is based on the model forms shown in Appendix 6 of BS 7671: 2018 (as ar @ Copyright Certsure LLP (August 2024)	mended) Enter a (🗸) or value in the respective fields, as app Where an item is not applicable insert N/A	ropriate. Please see the 'Notes for Recipients' Page 1 of 9



EICR18\_3C

**Original** (to the person ordering the work)

# **ELECTRICAL INSTALLATION CONDITION REPORT**

PART 5 : OBSERVATIONS					
One of the following Codes, as appropriate, has been allocated to each of the observations made below to indicate to the person(s) responsible for the electrical installation the degree of urgency for remedial action:	Code C1 Danger Present Risk of injury. Immediate remedi action required	al <b>Code C2 Potentially Dangero</b> Urgent remedial action require		Further	Code FI Investigation Required
Referring to the Schedule of Items Inspected (see PART 9), the attached Schedule of Circuit Details and Te	est Results (see PART 11A & 11B), and sub	ject to any <b>agreed limitations</b> listed in PAF	T 6 -		
No remedial action is required ( K), <b>OR</b> The following observations are made:					
	Observation(s)			Code	Location Reference
(.1) (4.144.17 RCDs/RCBOs in the consumer unit are type AC (possible DC I				( <u>C3</u> )	(Consumer unit )
(.2) (4.164.19 Absence of Arc fault protection for socket circuits (if HMO prope				(.C3)	(Installation)
() (			)	()	()
() (			)	()	()
() (			)	()	()
() (			)	()	()
() (			)	()	()
() (			)	()	()
() (			)	()	()
() (			)	()	()
() (			)	()	()
() (			)	()	()
() (			)	()	()
() (			)	()	()
() (			)	()	()
() (			)	()	()
() (			)	()	()
() (			)	()	()
() (			)	()	()
() (			,	()	()
				e page numbers	
Immediate remedial action required for items: ( <u>N/A</u>		provement recommended for items:	(.1,2		
Urgent remedial action required for items: ( .N/A	) Fu	rther investigation required for items:	( .N/A	•••••	)



**EICR18.3C** 

# **ELECTRICAL INSTALLATION CONDITION REPORT**

Issued in accordance with BS 7671: 2018 (as amended) - Requirements for Electrical Installations

# Original (to the person ordering the work)

### PART 6 : DETAILS AND LIMITATIONS OF THE INSPECTION AND TESTING

The inspection and testing has been carried out in accordance with BS 7671: 2018, as amended to ... 2024.......(date). Cables concealed within trunking and conduits, or cables and conduits concealed under floors, in inaccessible roof spaces and generally within the fabric of the building or underground, have not been visually inspected unless specifically agreed between the Client and the Inspector prior to inspection.

Details of the electrical installation covered by this report: A sample of all circuits within the installation have been tested and inspected unless otherwise noted.

(see additional page No.N/A. Agreed limitations including the reasons, if any, on the inspection and testing (653.2): No live to neutral insulation resistance tests carried out to prevent damage to connected equipment. No test or inspection has been undertaken in any building voids/loft spaces. see continuation sheet for more..

Agreed with (print name):	CLIENT	
Extent of sampling: A minimum of 20% of accessories have been visually checked for compliance & 100% of distribution equipment.		(see additional page No.N/A)

Operational limitations including the reasons: Unable to determine size and type of main supply company fuse. Unable to remove spotlights without damage to decoration (see additional page No. N/A

### PART 7 : SUPPLY CHARACTERISTICS AND EARTHING ARRANGEMENTS

System type and earthing arr	rangements		Number and type of live conductors		Nature of supply parameters		<sup>[1]</sup> By enquiry
TN-C: (N/A)	TN-S: (🖌 )	TN-C-S: ( N/A)	AC 1-phase, 2-wire: ()	2-phase, 3-wire: (	Nominal voltage between lines, U <sup>[1]</sup> :	( <u>N/A</u> ) V	<sup>[2]</sup> By enquiry or by
TT: (N/A	IT: (N/A)		3-phase, 3-wire: ( <mark>N/A</mark>	3-phase, 4-wire: (N/A	Nominal line voltage to Earth, $U_0$ <sup>[1]</sup> :	( <u>230</u> ) V	measurement
Supply protective device	. ,		DC 2-wire: (N/A) 3-wire: (N/A)	Other: (N/A)	Nominal frequency, <i>f</i> <sup>[1]</sup> :	( <b>50</b> ) Hz	
BS EN: (	– .N/A .		Confirmation of supply polarity:	()	Prospective fault current, Ipf [2]*:	( <b>1.77</b> ) kA	
BS EN: ()	Type: ( <mark>N/A</mark> )	Rated current: () A	Confirmation of supply polarity: Other sources of supply (Schedule of Test Results)	Page No: ( <mark>N/A</mark> )	External earth fault loop impedance, $Z_e$ <sup>[2]</sup> *:	( <mark>0.13</mark> ) Ω	

### PART 8 : PARTICULARS OF INSTALLATION REFERRED TO IN THIS REPORT

Maximum demand (load): (45) XX/A	Main protective conductors	Main protective bonding connections		Main switch / Switch-fuse / Circuit-breaker / RCD
(delete as appropriate)	Earthing conductor:	Water installation pipes:	(•••••••)	Location: (Within consumer unit
Means of Earthing	(material Copper)	Gas installation pipes:	(•••••••)	BS EN: (60947-3) Type: (3) Rating / setting of device: (N/A) A
Distributor's facility: ()	csa (1.6) mm <sup>2</sup> Connection/continuity	Structural steel:	(N/A)	No. of poles: (2) Current rating: (100) A Voltage rating: (230) V
Installation earth electrode(s): (N/A)	verified: ( 🖍 )	Oil installation pipes:	(N/A ()	
Earth electrode type - rod(s), tape, etc:	Main protective bonding conductors:	Lightning protection:	(N/A)	Where an RCD is used as the main switch
( <u>None</u> )	(material Copper)	Other (state):		RCD rated residual operating current, $I_{\Delta n}$ : (N/A) mA RCD Type: (N/A)
Location: ( N/A)	csa (1.0) mm <sup>2</sup> Connection/continuity	<u>N/A</u>	( <u>N/A</u> )	Rated time delay: $(N/A)$ ms Measured operating time: $(N/A)$ ms
Electrode resistance to Earth: $(N/A) \Omega$	verified: ( 🖌 )	<u>N/A</u>	( <u>N/A</u> )	

\*Where the installation is supplied by more than one source, the higher or highest values of prospective fault current, Iof, and external earth fault loop impedance, Ze, must be recorded.

All fields must be completed. Enter either, as appropriate: '\screw' if Acceptable condition; 'N/A' if Not applicable; 'LIM' if a Limitation exists, or Code appropriately: CODE 'C1', 'C2', 'C3' or 'FI' (codes to be recorded in PART 5, with additional comments (where appropriate) on attached numbered sheets)



EICR18.3C

# **ELECTRICAL INSTALLATION CONDITION REPORT**

Issued in accordance with BS 7671: 2018 (as amended) - Requirements for Electrical Installations

PA	RT 9 : SCHEDULE OF ITEMS INSPECTED (en	ter 🗸 , N//	A or (	Classification Code C1, C2, C3 or FI, as applicable)				
An ou	Intake equipment (visual inspection only) tcome against an item in section 1.1, other than access to live parts, should not be			Accessibility of all protective bonding connections (543.3.2) Provision of earthing / bonding labels at all appropriate locations (514.13.1)		4.16	Confirmation that integral test button / switch, where present, causes AFDD to trip when operated (643.10)	( <u>C3</u> )
	mine the overall assessment of the installation. Where inadequacies are identifie d be put against the appropriate item and a comment made in Part 5 of this repoi			FELV - requirements satisfied (411.7)	(N/A)	4.17	Presence of diagrams, charts or schedules at or near equipment, where required (514.9.1)	(•)
1.1	Distributor / supplier intake equipment			Other methods of protection e any of the methods listed below are employed, details should be provided on separate	shaats	4.18	Presence of alternative supply warning notice at or near equipment,	NI/A
	Service cable Service head	( <b>/</b> ) ( <b>/</b> )		Non-conducting location (418.1)	(N/A)	410	where required (514.15) Presence of next inspection recommendation label,	(N/A ()
	Earthing arrangement	( <b>v</b> )		Earth-free local equipotential bonding (418.2)	(N/A)	4.19	where required (514.12.1)	(
	Meter tails	( <b>v</b> )	•	Electrical separation (413; 418.3)	(N/A)	4.20	Presence of other required labelling (please specify) (514)	(N/A)
	Metering equipment	( <b>/</b> )	•	Double insulation (412)	(N/A)	4.21	Compatibility of protective devices, bases and other components;	
•	Isolator, where present	(N/A)		Reinforced insulation (412)	( <u>N/A</u> )		correct type and rating (no signs of unacceptable thermal damage, arcing or overheating) (432; 433; 434)	(
	inadequacies in the intake equipment are encountered, which may result in a dangero		•	Provisions where automatic disconnection of supply is not feasible (419)	( <u>N/A</u> )	4 22	Single-pole switching or protective devices in line conductors only	()
	tially dangerous situation, the person ordering the work and / or dutyholder must be inl rongly recommended that the person ordering the work informs the appropriate author		4.0	Distribution equipment, including consumer units and distribution be		7122	(132.14.1; 530.3.3)	()
12	Consumer's isolator, where present	(N/A ()	4.1	Adequacy of working space / accessibility to equipment (132.12; 513.1)	()	4.23	Protection against mechanical damage where cables enter equipment	
1.2	Consumer's meter tails	() ( <b>/</b> )		Security of fixing (134.1.1)	()		(522.8.1; 522.8.5; 522.8.11)	()
2.0	Presence of adequate arrangements for parallel or switched alternativ			Condition of insulation of live parts (416.1)	( <b>/</b> )	4.24	Protection against electromagnetic effects where cables enter ferromagnetic enclosures (521.5.1)	(
2.1	Adequate arrangements where a generating set operates as a switched	0 3001003	4.4 4.5	Adequacy security of barriers or enclosures (416.2.3) Condition of enclosure(s) in terms of IP rating, etc. (416.2)	( <b>)</b>	4.25	Confirmation that ALL conductor connections, including connections to	(,
	alternative to the public supply (551.6)	(N/A)		Condition of enclosure(s) in terms of fire rating, etc. (421.1.201; 421.1.6; 526.5)	()		busbars, are correctly located in terminals and are tight and secure (526.1)	(••••••)
2.2	Adequate arrangements where a generating set operates in parallel	NI/A	4.7	Enclosure not damaged / deteriorated so as to impair safety (651.2)	( <b>/</b> )	5.0	Distribution circuits	
	with the public supply (551.7)	(N/A)	4.8	Presence and effectiveness of obstacles (417.2)	(	5.1	Identification of conductors (514.3)	(N/A ()
3.0	Methods of protection		4.9	Presence of main switch(es), linked where required (462.1; 462.1.201; 462.2)	(	5.2	Cables correctly supported throughout their run (521.10.202; 522.8.5)	(N/A ()
3.1	Automatic disconnection of supply (ADS)		4.10	Operation of main switch(es) (functional check) (643.10)	( <b>V</b> )	5.3	Condition of insulation of live parts (416.1)	(N/A)
	Main earthing / bonding arrangement (411.3; Chap. 54) Presence of distributor's earthing arrangement (542.1.2.1; 542.1.2.2), or	()	4.11	Manual operation of circuit-breakers, RCDs and AFDDs to prove		5.4	Non-sheathed cables protected by enclosure in conduit, ducting or	<sub>(</sub> Ν/Α )
-	presence of installation earth electrode arrangement (542.1.2.); 542.1.2.)	( <b>/</b> )	410	functionality (643.10)	()		trunking (521.10.1)	(')
	Adequacy of earthing conductor size (542.3; 543.1.1)	()	4.12	Confirmation that integral test button / switch causes RCD(s) to trip when operated (functional check) (643.10)	(	5.5	Suitability of containment systems for continued use (including flexible conduit) (522)	N/A ()
•	Adequacy of earthing conductor connections (542.3.2)	()	4.13	RCD(s) provided for fault protection - includes RCBOs		5.6	Cables correctly terminated in enclosures (526)	(N/A)
•	Accessibility of earthing conductor connections (543.3.2)	()		(411.4.204; 411.4.5; 411.5.2; 531.2)	(N/A)	5.7	Examination of cables for signs of unacceptable thermal or mechanical	
•	Adequacy of main protective bonding conductor sizes (544.1.1)	()	4.14	RCD(s) provided for additional protection / requirements, where required -	(C3)		damage / deterioration (421.1; 522.6)	( <mark>N/A</mark> )
•	Adequacy and location of main protective bonding conductor connections (544.1.2)	()	4.15	includes RCBOs (411.3.3; 415.1) Presence of RCD six-monthly test notice, where required (514.12.2)	() ()	5.8	Adequacy of cables for current-carrying capacity with regard for the type and nature of installation (523)	( <mark>N/A</mark>

(' (' ') Original (to the person ordering the work)



EICR18.3C

# **ELECTRICAL INSTALLATION CONDITION REPORT**

5.9	Adequacy of protective devices; type and rated current for fault protection	N/A	6.2	Cables correctly supported throughout their run (521.10.202; 522.8.5)	()	•	*For cables concealed in walls / partitions containing metal parts	,N/A
	(411.3)	()	6.3	Condition of insulation of live parts (416.1)	()		regardless of depth (522.6.203)	('
0 1	Presence and adequacy of circuit protective conductors (411.3.1.1; 543.1) Coordination between conductors and overload protective devices	(N/A ()	6.4	Non-sheathed cables protected by enclosure in conduit, ducting or trunking (521.10.1)	(N/A)	•	*For final circuits supplying luminaires within domestic (household) premises (411.3.4)	(•
2	(433.1; 533.2.1) Cable installation methods / practices with regard to the type and nature of	( <mark>N/A</mark>	6.5	Suitability of containment systems for continued use (including flexible conduit) (522)	<ul> <li></li> </ul>	* Old	er installations designed prior to BS 7671: 2018 may not have required RCDs for additions	al protec
<u>-</u>	installation and external influences (522)	N/A ()	6.6	Adequacy of cables for current-carrying capacity with regard for the type	()	6.14	Provision of fire barriers, sealing arrangements and protection against thermal effects (527)	(
3	Where exposed to direct sunlight, cable of a suitable type (522.11.1)	(N/A ()		and nature of installation (523)	( <b>)</b>	615	Band II cables segregated / separated from Band I cables (528.1)	(
1	Cables concealed under floors, above ceilings, in walls / partitions, adequately protected against damage (522.6.201; 522.6.202;		6.7	Adequacy of protective devices; type and rated current for fault protection (411.3)	()	6.16		(
	522.6.203; 522.6.204) -		6.8	(411.5) Presence and adequacy of circuit protective conductors (411.3.1.1; 543.1)	() ( <b>/</b> )	6.17	Termination of cables at enclosures - identify / record numbers and	·
•	Installed in prescribed zones (see Section D. <i>Extent and limitations</i> ) (522.6.202)	(N/A	6.9	Co-ordination between conductors and overload protective devices (433.1; 533.2.1)	( <b>/</b> )		locations of items inspected (526) – Connection under no undue strain (526.6)	(
	Incorporating earthed armour or sheath, or run within earthed wiring		6.10	Wiring system(s) appropriate for the type and nature of the installation		•	No basic insulation of a conductor visible outside enclosure (526.8)	(
	system, or otherwise protected against mechanical damage by nails,	N/A	0.10	and external influences (522)	( <b>/</b> )	-	Connections of live conductors adequately enclosed (526.5)	(
	screws and the like (see Section D) (522.6.201; 522.6.204)	( <mark>N/A</mark>	6.11	Where exposed to direct sunlight, cable of a suitable type (522.11.1)	( <b>/</b> )	•	Adequately connected at point of entry to enclosure (glands, bushes, etc.)	)
	Provision of fire barriers, sealing arrangements and protection against thermal effects (527)	(N/A ()	6.12	Cables concealed under floors, above ceilings, in walls / partitions,			(522.8.5)	(
	Band II cables segregated / separated from Band I cables (528.1)	(N/A ()		adequately protected against damage (522.6.201; 522.6.202; 522.6.203; 522.6.204) –		6.18	Condition of accessories including socket-outlets, switches and joint boxes (651.2)	(
	Cables segregated / separated from non-electrical services (528.3)	(N/A ()		Installed in prescribed zones (see Section D. Extent and limitations)		6.19	Suitability of accessories for external influences (512.2)	(
	Condition of circuit accessories (651.2)	(N/A ()		(522.6.202)	(LIM ()	6.20	Single-pole switching or protective devices in line conductors only	
	Suitability of circuit accessories for external influences (512.2)	(N/A ()	•	Incorporating earthed armour or sheath, or run within earthed wiring			(132.14.1; 530.3.3)	(
	Single-pole switching or protective devices in line conductors only	,N/Α		system, or otherwise protected against mechanical damage by nails, screws and the like (see Section D) (522.6.201; 522.6.204)	(N/A ()	7.0	Isolation and switching	
	(132.14.1; 530.3.3)	()	613	Provision of additional protection by RCD having rated residual operating	()	7.1	Isolators -	
	Adequacy of connections, including cpcs, within accessories and to fixed and stationary equipment - identify / record numbers and		0.15	current not exceeding 30 mA -		•	Presence and condition of appropriate devices (462; 537.2)	(
	locations of items inspected (526)	(N/A ()	-	*For all socket-outlets of rating 32 A or less (411.3.3)	()	•	Acceptable location - state if local or remote from equipment in question	(
	Presence, operation and correct location of appropriate devices for isolation and switching (Chap. 46; 537)	N/A		tional protection by RCD may not have been provided as a noted exception in ain non-domestic installations covered by indent (ii) of Regulation 411.3.3.			(462; 537.2.7) Capable of being secured in the OFF position (462.3)	(
;	General condition of wiring system (651.2)	N/A ()		*For the supply of mobile equipment not exceeding 32 A rating		•	Correct operation verified (643.10)	(
	Temperature rating of cable insulation (522.1.1; Table 52.1)	N/A ()		for use outdoors (411.3.3)	(•••••••)	•	Clearly identified by position and / or durable marking (537.2.7)	(
		. /	•	*For cables concealed in walls at a depth of less than 50 mm	, <b>/</b> .	•	Warning label posted in situations where live parts cannot be isolated	,N/
6.0	Final circuits Identification of conductors (514.3)			(522.6.202)	()		by the operation of a single device (514.11.1; 5371.2)	



EICR18.3C

# **ELECTRICAL INSTALLATION CONDITION REPORT**

Issued in accordance with BS 7671: 2018 (as amended) - Requirements for Electrical Installations

PA	RT 9 : SCHEDULE OF ITEMS INSPECTED (er	nter ✓, N/	A or	Classification Code C1, C2, C3 or FI, as applicable)				
7.2	Switching off for mechanical maintenance -		8.5	Security of fixing (134.1.1)	()	•	Low voltage (e.g. 230 volt) socket-outlets sited at least 2.5 m from	
•	Presence and condition of appropriate devices (464.1; 537.3.2)	()	8.6	Cable entry holes in ceiling above luminaires, sized or sealed so as to			zone I (701.512.3) (	
•	Capable of being secured in the OFF position where not under continuous supervision (464.2)	()		restrict the spread of fire: list number and location of luminaires inspected (separate page) (527.2)	( <b>)</b>	•	Suitability of equipment for external influences for installed location in terms of IP rating (701.512.2)	)
•	Correct operation verified (643.10)	()	8.7	Recessed luminaires (downlighters) -		•	Suitability of accessories and controlgear etc. for a particular	
•	Clearly identified by position and / or durable marking (537.3.2.4)	()	•	Correct type of lamps fitted (559.3.1)	(LIM ()		zone (701.512.3) (	)
7.3	Emergency switching off –		•	Installed to minimise build-up of heat by use of "fire rated" fittings,	(LIM	•	Suitability of current-using equipment for particular position within the location (701.55)	/ \
•	Presence and condition of appropriate devices (465; 537.3.3; 537.4)	(N/A ()		insulation displacement box or similar (421.1.2)	() , LIM	9.2	the location (701.55) ( Other special installations or locations –	)
•	Readily accessible for operation where danger might occur (537.3.3.6)	(N/A ()	•	No signs of overheating to surrounding building fabric (559.4.1)	() ,LIM	5.2	N/A (N/A	
•	Correct operation verified (643.10)	(N/A ()	-	No signs of overheating to conductors / terminations (526.1)	()		1	、 、
•	Clearly identified by position and / or durable marking	N/A 、	9.0	Special locations and installations				,
	(537.3.3.5; 537.3.3.6; 537.4.3; 537.4.4)	()		e special installations or locations relating to a particular Section of Part 7, an additiona	I Inspection			,
7.4	Functional switching -	,	Sche	dule(s) should be provided on separate pages.			(	,
•	Presence and condition of appropriate devices (537.3.1.1; 537.3.1.2)	()	9.1	Location(s) containing a bath or shower -			(	
•	Correct operation verified (643.10)	()	•	Additional protection by RCD having rated residual operating current not		10.0	Prosumer's low voltage installation (N/A)	)
8.0	Current-using equipment (permanently connected)			exceeding 30 mA for all low voltage (LV) circuits serving the location or passing through zones 1 and / or 2 of the location (701.411.3.3)	()		re elements of a prosuming installation falling within the scope of Chapter 82 are covered by the rt, additional schedules detailing the associated inspection and testing should be provided on	
8.1	Condition of equipment in terms of IP rating, etc.	()	•	Where used as a protective measure, requirements for SELV or PELV	,N/A 、		rt, additional schedules detailing the associated inspection and testing should be provided on rate pages.	
	(416.2; 422.3; 422.4; 522.4)	() ( <b>V</b> )		met (701.414.4.5)	(IN/A ()			—
8.2	Equipment does not constitute a fire hazard (421)	()	•	Shaver supply units complying with BS EN 61558-2-5 formerly BS 3535	,N/A 、		edule of Items Inspected by	
8.3	Enclosure not damaged / deteriorated so as to impair safety	()		(701.512.3)	()	Nam	ne (capitals): THOMAS BURDETT	.
8.4	(134.1.1; 416.2) Suitability for the environment and external influences (512.2)	() ()	•	Presence of supplementary bonding conductors, unless not required by <i>BS 7671: 2018</i> (701.415.2)	(N/A ()	Sign	nature: Date:	···-
PA	RT 10 : SCHEDULES AND ADDITIONAL PAG	ES (the p	ages	s identified are an essential part of this report (see Regi	ulation 65	3.2))		

### Schedule of Inspections Schedule of Circuit Details and Test Additional pages, including data sheets Special installations or locations Schedules relating to Prosumer's **Continuation sheets** Results for the installation for additional sources (indicated in item 9.2 above) installations (indicated in item 10 above) 4,5&6 (.....7&8 (9.....) (None (None (None Page No(s): Page No(s): Page No(s): Page No(s): Page No(s): .....) .....) Page No(s):



# **ELECTRICAL INSTALLATION CONDITION REPORT**

Issued in accordance with BS 7671: 2018 (as amended) - Requirements for Electrical Installations

PA	RT 11A : SCHEDULE OF CIRCUIT DETAILS	<b>6 (</b> GO ТО	Part 11B	'Schedule	of Test F	Results' to	enter te	st results for the	e corresp	onding c	ircuit liste	d in this pa	art)							
		r11B)	ро	erved		conductor er & csa)	Max. disconnection time (BS 7671)		Overcurre	ent protective de	evice			RCD						
Circuit number	Circuit description	Type of wiring (see footer to PART 11B)	Reference Meth (BS 7671)	Reference Meth (BS 7671) Number of points s		Reference Method (BS 7671) (BS 7671) Number of points served		Reference Methr (BS 7671) (BS 7671) Number of points se		Live cpc		BS (EN)	BS (EN) Type		Short- circuit capacity (kA)	Maximum permitted Zs* (Ω)	BS (EN)	Туре	Rating (A)	Operating current, I <sub>dn</sub> (mA)
	RCD	N/A	N/A	N/A	N/A	N/A	0.4	N/A	N/A	N/A	N/A	N/A	61008	A	80	30				
	RCD	N/A	N/A	N/A	N/A	N/A	0.4	N/A	N/A	N/A	N/A	N/A	61008	A	80	30				
1	Shower	A	с	1	6	2.5	0.4	60898	В	40	6	1.09	N/A	N/A	N/A	N/A				
2	Downstairs sockets	А	с	8	2.5	1.5	0.4	60898	в	32	6	1.37	N/A	N/A	N/A	N/A				
3	Upstairs lights and smoke alarms	A	101	11	1	1	0.4	60898	в	6	6	7.28	N/A	N/A	N/A	N/A				
4	Downstairs lights and smoke alarms	А	С	21	1	1	0.4	60898	В	6	6	7.28	N/A	N/A	N/A	N/A				
5	Surge protection device	N/A	N/A	N/A	N/A	N/A	N/A	61643	2	N/A	N/A	N/A	N/A	N/A	N/A	N/A				
6	Surge protection device	N/A	N/A	N/A	N/A	N/A	N/A	61643	2	N/A	N/A	N/A	N/A	N/A	N/A	N/A				
	RCD	N/A	N/A	N/A	N/A	N/A	0.4	N/A	N/A	N/A	N/A	N/A	61008	AC	63	30				
	RCD	N/A	N/A	N/A	N/A	N/A	0.4	N/A	N/A	N/A	N/A	N/A	61008	AC	63	30				
7	Cooker	А	с	2	6	2.5	0.4	60898	В	32	6	1.37	N/A	N/A	N/A	N/A				
8	Upstairs sockets	A	с	10	2.5	1.5	0.4	60898	В	32	6	1.37	N/A	N/A	N/A	N/A				
9	Kitche sockets	А	с	6	2.5	1.5	0.4	60898	В	32	6	1.37	N/A	N/A	N/A	N/A				
10	Central heating	A	С	1	1.5	1	0.4	60898	В	6	6	7.28	N/A	N/A	N/A	N/A				
DB ( Loc Cor <b>SPI</b>	STRIBUTION BOARD (DB) DETAILS (complete in every c         designation.DB-01         ation of DB: Front bed $Z_{db}$ : 0.13       ( $\Omega$ ) $I_{pf}$ at DB+1.77         firmation of supply polarity: (,)       Phase sequence confirmed <sup>4</sup> P Details** Types: TI (N/A)       T2 (,)       T3 (N/A)       N/A         us indicator checked (where functionality indicator is present):	(kA) (N/A ) (N/A	device is Type brac Where T3 to protect details in (See Sect	mbined T1 installed, in kets.	dicate by ti e installed quipment, s' (PART 11E further det	icking both on a circuit enter 3), rails).	Supply to Overcurr BS (EN): ( Associate	OMPLETED ONL DB is from: N/A ent protective devic N/A ed RCD (if any) N/A	e for the d	stribution c	<b>ircuit</b> Nominal vol <sup>.</sup>	tage: (N/A	.) V Rating: (N/A	)A N	lo. of phases	s: ( <mark>N/A</mark> )				

This report is based on the model forms shown in Appendix 6 of *BS 7671: 2018* (as amended) @ Copyright Certsure LLP (August 2024)

Enter a ( $\checkmark$ ) or value in the respective fields, as appropriate. Where an item is not applicable insert N/A <sup>†</sup> Where applicable. \*Where figure is not taken from *BS 7671*, state source: **N**/A....

EICR18\_3C

Page 7 of 9



EICR18.3C

# **ELECTRICAL INSTALLATION CONDITION REPORT**

			Continuity (C	1)		Ins	Insulation resistance			oop , Zs	R	CD	AFDD**						
	Ring final circuits only (measured end to end)			All circuits (complete at least column)		Live / Live	Live / Earth	Test Collage DC		Max. measured earth fault loop impedance, Zs	Operating time*	Test button	AFDD test button		Comments and additional inform	ation, where required			
	(Line) r <sub>1</sub>	(Neutral) r <sub>n</sub>	(cpc) r <sub>2</sub>	(R <sub>1</sub> + R <sub>2</sub> )	R <sub>2</sub>	(MΩ)	(MΩ)	(V)	(√)	(Ω)	(ms)	(√)	(√)						
	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	V	N/A	87.1	~	N/A	N/A					
	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	V	N/A	87.1	V	N/A	N/A					
	N/A	N/A	N/A	0.29	N/A	LIM	50	500	V	0.42	N/A	N/A	N/A	N/A					
	0.48	0.48	0.80	0.37	N/A	LIM	50	500	V	0.47	N/A	N/A	N/A	N/A					
	N/A	N/A	N/A	0.75	N/A	LIM	50	500	V	0.88	N/A	N/A	N/A	N/A					
	N/A	N/A	N/A	0.79	N/A	LIM	50	500	~	0.92	N/A	N/A	N/A	N/A					
	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A					
	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	V	N/A	22.8	~	N/A	N/A					
	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	V	N/A	22.8	~	N/A	N/A					
	N/A	N/A	N/A	0.19	N/A	LIM	100	500		0.32	N/A	N/A	N/A	N/A					
		-		0.46	0.47		0.40 0.26	N/A	LIM LIM	100 100	500	V	0.55	N/A	N/A	N/A	N/A		
		0.34					N/A			500	V	0.38	N/A	N/A	N/A	N/A			
_	N/A	N/A					0.21	0.21	N/A	LIM	100	500	~	0.34	N/A	N/A	N/A	N/A	
_																			
_																			
1	uits/equipm	nent vulnerab	le to damage	e when testir	ıg (where ap	plicable): N/	Ά												
			-							El a atria						00/05/0005			
E	STED BY	Name (	capitals):		URDETT				Positio	n: Electric	lan			Signature: .	HAB	Date: 08/05/2025			
E	ST INSTR	UMENTS (	ENTER SE	RIAL NUM	<b>BER AGA</b>	INST EACH	I INSTRUM	<b>IENT USEI</b>	D)										
uŀ	ti-function:			Conti	nuity:			Insulatio	on resist	ance:		Ear	rth fault lo	op impedance:	Earth electrode resistance:	RCD:			
0	2092619			N/A				N/A				. <u>N/</u>	Ά		N/A	N/A			
D	effectiven	ness is verifi	ed using ar	n alternating	g current te	est at rated	residual op	erating curr	ent (I <sub>∆n</sub> )	)				ot all AFDDs have a test fur and additional information		AFDD this should be stated in the field for			
ļ	S for Type of	wiring (A)	Thermoplast / sheathed c	ic insulated	B) Thermopl	astic cables	C) Thermopla	astic cables	(D) The	rmoplastic cable netallic trunking		hermoplastic	cables in			neral-insulated cables Other (state):N/A			



N18.3c

# **GENERAL CONTINUATION SHEET**

Issued in accordance with BS 7671: 2018 (as amended) – Requirements for Electrical Installations

### NOTES

### Agreed limitations

Accessories such as sockets and light switches not unscrewed where decor may be damaged.

Fixed equipment such as cookers, or other hard wired equipment tested at point of isolation.

Socket-outlets or connection points behind washing-machines, dishwashers, cooker-hoods etc not inspected or tested.

Only wiring that can be reasonably accessed has been visually inspected.

Circuits incorporating integrated appliances only tested at isolation spur unit and not at socket outlet behind appliance to prevent damage to goods and floor areas where moving would be required.

Central heating system including wiring to thermostats and control / wiring centres not inspected - tested to isolation point only.

Zs values may be calculated to prevent access to exposed live parts during testing

Unable to determine whether cables are routed in prescribed cable zones due to building fabric (plaster etc)

9

# **NOTES FOR RECIPIENT**

## THIS CONDITION REPORT IS AN IMPORTANT AND VALUABLE DOCUMENT WHICH SHOULD BE RETAINED FOR FUTURE USE

The purpose of periodic inspection is to determine, so far as is reasonably practicable, whether an electrical installation is in a satisfactory condition for continued service. This report provides an assessment of the condition of the electrical installation identified overleaf at the time it was inspected and tested, taking into account the stated extent of the installation and the limitations of the inspection and testing.

This report has been issued in accordance with the national standard for the safety of electrical installations, *BS 7671: 2018* (as amended) – Requirements for Electrical Installations.

The report identifies any damage, deterioration, defects and/or conditions found by the inspector which may give rise to danger (see PART 5), together with any items for which improvement is recommended.

You should have received the report marked 'Original' and the contractor should retain a duplicate. If you were the person ordering this report, but not the owner or user of the installation, you should pass this report, or a full copy of it, including these notes, the schedules and additional pages (if any), immediately to the owner or user of the installation.

This report should be retained in a safe place and shown to any person inspecting or undertaking further work on the electrical installation in the future. If you later vacate the property, this report will provide the new user with an assessment of the condition of the electrical installation at the time the periodic inspection was carried out.

For safety reasons, the electrical installation should be re-inspected at appropriate intervals by a skilled person or persons, competent in such work. NICEIC\* recommends that you engage the services of an NICEIC contractor for the inspection. Only an NICEIC contractor is authorised to issue this NICEIC Electrical Installation Condition Report, which has a unique serial number that is traceable to the contractor to which it was supplied by NICEIC.

The recommended date by which the next inspection should be carried out is stated in PART 4 of this report. With the exception of domestic (household) premises, there should also be a notice at or near the main switchboard or distribution board/consumer unit indicating when the next inspection of the installation is due.

This report is intended to be issued only for the purpose of reporting on the condition of an existing electrical installation and must not be issued to certify new electrical installation work including the replacement of a distribution board or consumer unit.

The report consists of at least eight numbered pages. The report is only valid if the Schedule of Items Inspected (PART 9) has been completed to confirm that all relevant inspections have been carried out and the Schedule of Circuit Details (PART 11A) and the Schedule of Test Results (PART 11B) are attached. For installations having more than one distribution board (or consumer unit) or more circuits than can be recorded in PARTS 11A & 11B, one or more additional Schedule of Circuit Details and Schedule of Test Results, should form part of the report. Additional numbered pages may have been provided to permit further relevant information relating to the installation to be recorded. The report is invalid if any of the additional pages, listed in PART 10 are missing.

Where the installation includes a residual current device (RCD) it should be tested every six months by pressing the button marked "T" or "Test". The device should switch off the supply and should then be switched on to restore the supply. If the device does not switch off the supply when the button is pressed, seek expert advice. For safety reasons it is important that this instruction is followed.

Where the installation includes an arc fault detection device (AFDD) having a manual test facility it should be tested six-monthly by pressing the test button. Where an AFDD has both a test button and automatic test function, manufacturer's instructions should be followed with respect to test button operation.

Where the installation includes a surge protection device (SPD) the status indicator should be checked to confirm it is in operational condition in accordance with manufacturer's information. If the indication shows that the device is not operational, seek expert advice.

Where the installation can be supplied by more than one source, such as the public supply and a standby generator or microgenerator, this should be identified in PART 7 Supply Characteristics and Earthing Arrangements, and the Schedules of Circuit Details and Schedule of Test Results (PARTS 11A & 11B) compiled accordingly.

PART 6 (Details and limitations) should identify fully the extent of the installation covered by this report and any limitations on the inspection and testing. The inspector should have agreed these aspects with the person ordering the report and with other interested parties (licensing authority, insurance company, mortgage provider and the like) before the inspection was carried out.

Operational limitations may have been encountered during the inspection such as inability to gain access to parts of the installation or to an item of equipment. The inspector should have noted any such limitations in PART 6. It should be noted that the greater the limitations applying to a report, the less its value from the safety aspect.

A declaration should have been given by the inspector in PART 4 of the report. The declaration must reflect the statement given in PART 3, which summarises the observations and recommendations made in PART 5. Where one or more observations have been made in PART 5, the Classification code given to each by the inspector indicates the degree of urgency with which remedial action needs to be taken to restore the installation to a safe working condition.

Where the inspector has indicated an observation as code C1 (danger present) the safety of those using the installation is at risk. Wherever practicable, items classified as C1 should be made safe on discovery, and it is recommended that a skilled person(s) competent in electrical installation work undertakes the necessary remedial work immediately.

Where the inspector has indicated an observation as code C2 (potentially dangerous) the safety of those using the installation may be at risk, and it is recommended that a skilled person competent in electrical installation work undertakes the necessary remedial work as a matter of urgency.

Where the inspector has indicated that an item requires further investigation (FI), the investigation should be carried out without delay to determine whether danger or potential danger exists. For further guidance on the Classification codes, please see the reverse of page 2.

Where inadequacies in the intake equipment have been observed (Item 1 of PART 9), the person ordering the inspection should inform the distributor and/or supplier as appropriate.

Should the person ordering this report have reason to believe that it does not reasonably reflect the condition of the electrical installation reported on, that person should in the first instance raise the specific concerns in writing with the contractor. If the concerns remain unresolved, the person ordering this report may make a formal complaint to NICEIC, for which purpose a complaint form is available on request.

The complaints procedure offered by NICEIC is subject to certain terms and conditions, full details of which are available upon application. NICEIC does not investigate complaints relating to the operational performance of electrical installations (such as lighting levels), or to contractual or commercial issues (such as time or cost).

# For further information about electrical safety and how NICEIC can help you, visit: WWW.NICEIC.com

\* NICEIC is operated by Certsure LLP, a partnership between the Electrical Contractors' Association and the charity, Electrical Safety First. NICEIC maintains and publishes registers of electrical contractors that it has assessed against particular scheme requirements (including the technical standard of electrical work).

# **GUIDANCE FOR RECIPIENTS ON THE CLASSIFICATION CODES** ONLY ONE CLASSIFICATION CODE SHOULD BE GIVEN FOR EACH RECORDED OBSERVATION

### Classification code C1 (Danger present)

Where an observation has been given a Classification code C1, the safety of those using the installation is at risk and immediate remedial action is required.

The person responsible for the maintenance of the installation is advised to take action without delay to remedy the observed deficiency in the installation, or to take other appropriate action (such as switching off and isolating the affected part(s) of the installation) to remove the danger. The NICEIC contractor issuing this report will be able to provide further advice.

NICEIC makes available 'Electrical Danger Notification' forms to enable inspectors to record, and then to communicate to the person ordering the report, any dangerous condition discovered.

### Classification code C2 (Potentially dangerous)

Classification code C2 indicates that, whilst those using the installation may not be at immediate risk, urgent remedial action is required to remove potential danger. The NICEIC contractor issuing this report will be able to provide further advice.

It is important to note that the recommendation given for the next inspection date in PART 4 of this report is conditional upon all items which have been given a Classification code C1 and code C2 being remedied immediately and as a matter of urgency, respectively.

It would not be reasonable for the inspector to indicate that the installation is in a satisfactory condition if any observation in this report has been given a code C1 or code C2 classification.

### Classification code C3 (Improvement recommended)

Where an observation has been given a Classification code C3, the inspection and/or testing has revealed a noncompliance with the current safety standard which, whilst not presenting immediate or potential danger, would result in a significant safety improvement if remedied. Careful consideration should be given to the safety benefits of improving these aspects of the installation. The NICEIC contractor issuing this report will be able to provide further advice.

### Code FI (Further investigation required without delay)

It should usually be possible for the inspector to attribute a Classification code to each observation without indicating a need for further investigation.

However, where 'FI' has been entered against an observation the inspector considers that further investigation of that observation is likely to reveal danger or potential danger that, due to the agreed extent or limitations of the inspection and/or testing (entered in PART 6), could not be fully identified at the time.

It would not be appropriate for the inspector to indicate that the installation is in a satisfactory condition if there is reasonable doubt as to whether danger or potential danger exists. Consequently, where the inspector has indicated 'Further investigation required without delay' (FI) the overall assessment of the installation (PART 3) should be marked as 'Unsatisfactory'.

If the inspector has indicated that an observation requires further investigation without delay, the person ordering this report is advised to arrange for the NICEIC contractor issuing the report (or another skilled person or persons competent in such work) to undertake further examination of that aspect of the installation as a matter of urgency, to determine whether or not danger or potential danger exists.

### **Further information**

Further information on the application of Classification codes, primarily aimed at inspectors but of possible interest to persons ordering condition reports, can be found in Electrical Safety First's Best Practice Guide No 4 *Electrical installation condition reporting: Classification Codes for domestic and similar electrical installations*. The guide can be viewed or downloaded free of charge from www.electricalsafetyfirst.org.uk

For further information about electrical safety and how NICEIC can help you, visit www.niceic.com