

## Landlord Gas Safety Record

Cert. No. 209

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure.

Company / Installer							Job Address							Customer / Landlord								
Engineer		Deklan Simpson												ne	(	Corrina						
Company Address		Simtec Plumbing And Heating					4						Con	npany	1	MBE Limited	ł					
		27 Stray road					Penyghent Avenue						Add	lress		villa farm wigginton road York						
							Yo	York														
		York													ì	York						
						Post Code	e YC	YO31 0QJ														
Post Code		YO31 0NE				Tel. No								t Code	ì	YO32 2RH						
Tel No.		07415903753											Tel.	No								
Gas Safe Reg		3916101																				
ID Card No.		3916101																				
		_						_														
Appliance Details									ction Details													
Locatio		n Appliance Type		Make	Mode	I Flue	Flue Type	Landlord's Appliance	llord's Appliance Inspected liance	Operating Pressure (mbar)	Heat Input (kW/h)	High Combus Reading		Low Comb Readir		n Safety device(s) correct	Provision	Visual condition of flue and	Performance	Appliance Serviced	Appliance safe to use	
												Ratio CO	CO2 %	Ratio CO	CO2	operation	satisfactory	termination satisfactory	test			
1	Kitcher	n l	Cooker	Beko	XTG6	53k	NA	Yes	Yes	na	12.7	<u> </u>		na na	-	Yes	Yes	NA	NA	NA	Yes	
2	Bedroor		Boiler	Ideal	Logic + Co		NA	Yes	Yes	19.7	30	0.0007 56				-	Yes	Yes	Pass	No	Yes	
3																						
4																						
5																						
6																						
Dei	fects / lde			Labels and Warning Notice Issued					CO Alarm(s)				Smoke Alarm(s)									
	1									NA												
2 3 4													СО	Alarm(	s) fitt	ted	Yes	Smoke Alarm(s) fitted		Yes		
														Alarm(			Pass		Smoke Alarm(s) tested and Satisfactory		Pass	
	5 6												and	d Satisfa	actor	У		and Sat	stactory			
	0																					
Em	ergency Cor	ntrol Acces	ssible Yes Gas	Tightness Satisfactory Yes	S	Comr	nents															
Gas Installation Pipework Visual Inspection Satisfactory Yes																						
	Equipotenti	ial Bonding	y Yes																			
NE	XT INSPEC	TION DUE	ON OR	10-May-2024																		
	FORE																					
Sig	natures																					
Iss	ued by:					Received S	Signed	1					[	Date 10-May-2023								
			VIII L	1	k	by:																
Pri	nt Name		Deklan Simpson	2	F	Print Name																
			Dekian Simpso	•																		