

This record can be used to document the outcomes of the checks and tests required by The Gas Safety (Installation and use) Regulations. Some of the outcomes are as a result of visual inspection only and are recorded where appropriate. Unless specifically recorded no detailed inspection of the flue lining, construction or integrity has been performed. Registered Business/engineer details can be checked at www.gassaferegister.co.uk or by calling 0800 408 5500

REGISTERED BUSINESS DETAILS Reg No: 157664

Gas Engineer Name: COLIN ROBERTSON
 Gas Safe registered engineer No: 157664
 Company: C. ROBERTSON
 Address: 19, LEIGHTON CROFT YORK
 Postcode: YO30529 Tel: 07710448500

INSPECTION / INSTALLATION ADDRESS

Name & Title: ADAM BENNETT LITTLE
 Address: 58, GULLYHEATH YORK
 Postcode: 611611 Tel: 611611

LANDLORD (OR AGENT) NAME & ADDRESS (if Applicable)

Name & Title: ADAM BENNETT LITTLE
 Address: 58, GULLYHEATH YORK
 Postcode: 611611 Tel: 611611

APPLIANCE DETAILS				FLUE TESTS				INSPECTION DETAILS								
Location	Make	Model	Type	Flue type OF/RS/FL	Operating pressure in Mbar or heat input kW/h or Btu/h	Safety device(s) correct operation Yes/No/NA	Spillage test Pass/Fail/NA	Smoke pellet flow test Pass/Fail/NA	Combustion analyser reading (if applicable) CO 102	Satisfactory termination Yes/No/NA	Flue visual condition Pass/Fail/NA	Adequate ventilation Yes/No	Landlord's appliance Yes/No/NA	Inspected Yes/No	Appliance serviced Yes/No	Appliance safe to use Yes/No
1	BACK ROOM	WOLFELETTA 287	HEF COMB.	RS	19 INCHES	YES	N/A	N/A	CO 102 0.001	YES	PASS	N/A	YES	YES	YES	YES
2																
3																
4																
5																

Gas Installation Pipework: Satisfactory Visual Inspection: PASS FAIL N/A

Emergency Control Accessible: PASS FAIL N/A

Satisfactory Gas Tightness Test: PASS FAIL N/A

Equipment Bonding Satisfactory: PASS FAIL N/A

Carbon Monoxide: Drowsiness, headaches or nausea when a gas appliance is running could be Carbon Monoxide (CO) poisoning. Turn the appliance off IMMEDIATELY and seek expert help.

CO Alarm(s) fitted: YES NO CO Alarm(s) tested: YES NO Make/Model: 41208 Date of Manufacture: 2021

GIVE DETAILS OF ANY FAULTS		RECTIFICATION WORK CARRIED OUT		WARNING NOTICE ISSUED		WARNING TAG OR STICKER FIXED	
				Yes/No/NA *		Yes/No/NA	
1	STARTING TO SHOW SIGNS OF AGE						
2	HAS HAD WATER LEAK INSIDE						
3							
4							

DESCRIPTION OF WORK CARRIED OUT

Print Name: [Signature] Date: 8/5/24

RECEIVED BY: [Signature] Signed: [Signature] Date: 8/5/24

ATTENTION Next Safety check due by: 8/5/25

NUMBER OF APPLIANCES TESTED

Copies: White - Landlord Pink - Customer / Tenant (if rented) Blue - Engineer