## säfe Direct Boiler Company

## **Landlord Gas Safety Record**

Cert. No. 2155

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure.

Compar	mpany / Installer					Job Address							Customer / Landlord						
Engineer	Paul Griffin			Name						Name			man						
Company	Direct Boiler Company			Address	1	117					Company Address								
Address	2	2 The Green, Back Street,				F	Fulford Road					112							
						Y	York					Fishergate							
		Driffield											York						
		Yorkshire				Y	O104BB												
Post Code	ost Code YO25 9RW			Tel. No							Post Code	YO104BB							
Tel No.	1025 51111										Tel. No								
	as Safe Reg 576489																		
ID Card N		576489																	
ID Card N	10.																		
Applian	ce Detai	ils					Inspec	tion Details											
	Location	Appliance Type	Make	Mode	el Flue T		e Landlord's Appliance	Appliance Inspected	Operating Pressure (mbar)	Heat Input (kW/h)		Reading 02 % Ratio CO CO		Ventilation Provision satisfactory	Visual condition of flue and termination satisfactory	Flue Performance test	Appliance Serviced	Appliance safe to use	
1 Ba	throom	Boiler	1Ideal	Ideal Logic	Combi 30	BF	Yes	Yes	17.99	NA	0008 75 8	9,000 ppm %		Yes	Yes	Pass	Yes	Yes	
2		Doner	Tideai	racar Logic	COMBI 30		165	103	17.55	10.0	0000 73	3.0 10.1 10.1 10	103	103	163	1 433	103	103	
3																			
4																			
5																			
6																			
Defects	/ Identi	fied							Labels a	and Warning No	otice Issued	CO Alarm(s			Smoke	Alarm(s	)		
J 0. 0 0 10	,										()	•			()	4			
1				nsion vessal	vessal NA					CO Marine (a) 5	Smake Alarm(s) fitted Ves								
3											CO Alarm(s) fitted No			Smoke Alarm(s) fitted Yes					
4												CO Alarm(s) te	ested		Smoke	Δlarm(s) te	sted		
5													and Satisfactory				Smoke Alarm(s) tested and Satisfactory		
6																			
Emergen	cy Control	Accessible Yes Gas	Tightness Satisfactory Ye	s	Comr	nents													
Gas Installation Pipework Visual Inspection Satisfactory Yes																			
Gas Insta	liation Pip	ework visual inspection	Satisfactory Yes																
Equipotential Bonding Yes																			
Water qu	ality/level	of inhibitor acceptable	NA																
NEXT INSPECTION DUE ON OR 26-Mar-2025 BEFORE																			
Ciau I																		<u> </u>	
					Received S by:	ceived Signed						Date 26-Mar-2024							
Print Nan	ne	Paul Griffin		r	Print Name		Mcma	naman											
		i dai Gillilli					PICITIO												