

Landlord Gas Safety Record

Cert. No. 11268

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure.

Company / I	npany / Installer						Job Address							Customer / Landlord							
Engineer	Paul R	Paul Richardson				Name Unknown								Mr Paul Blades							
Company	Nortor	Nortons Heating				Address 36				Compa	-										
Address	Suite 4a Heritage House					Se	Second Avenue						5	4							
	Osbaldwick					Yo	York							Hill Garth							
	York					Yo	York						,	York							
						Post Code YO31 0RX								York							
Post Code YO19 5UW					Tel. No	I. No						Post Co	de '	YO41 5BP							
Tel No. 01904411040												Tel. No									
Gas Safe Reg 199682																					
ID Card No. 5424730																					
Appliance D							tion Details														
Location	י	Appliance Type	Make	Mode	el	Flue Type	Landlord's Appliance	Appliance Inspected	Operating Pressure (mbar)	Heat Input (kW/h)	High Combusti Reading	on Low Combustion Reading		Safety device(s) correct	Provision	Visual condition of flue and	Performance	Appliance Serviced	Appliance safe to use		
											Ratio CO ppm	CO2 Ratio	CO CO2	operation	satisfactory	termination satisfactory	test				
1 Bathroo	om	Boiler	Worcester	Greenstar 80	000 Life 40	RS	Yes	Yes	17	40	0.0025 168				Yes	Yes	Pass	No	Yes		
2 Kitche			Lamona Hob	Lamo	na	FL	Yes	Yes	NA	NA	NA NA				Yes	NA	NA	No	Yes		
3																					
4																					
5																					
6																					
Defects / Identified						Labels and Warning Notice Issued					CO Alarm(s)				Smoke	Smoke Alarm(s)					
1										No											
2										No		CO Ala	rm(s) fitt	ted	Yes	Smoke /	Alarm(s) fit	ed	Yes		
3												60.41					• • • • • • • • • • • • • • • • • • • •				
	5										CO Alarm(s) tested and Satisfactory Pass			Smoke Alarm(s) tested and Satisfactory							
6														,		und out	.5.46.6.				
Emergency Co	ntrol Ac	cessible Yes Gas	Tightness Satisfactory Ye	S	Comr	ments															
Gas Installation Pipework Visual Inspection Satisfactory Yes																					
Equipotential Bonding Yes																					
Water quality/level of inhibitor acceptable Yes																					
NEXT INSPECTION DUE ON OR 05-Jun-2025 BEFORE 05-Jun-2025																					
Signatures Issued by: Print Name	Signe	d Paul Richardson		b	Received S by: Print Name	Signed	P. Rich	nardson				Date	à	30-M	ay-2024						