

Domestic/Landlord Gas Safety Record

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out.

Certificate Reference

Nick 31 178a Hull,Road

Certificate No: G.M.2905

Engineers Details					Insta	Installation Details					Client Details								
Trading Title Address		G M Plumbing And Heating 3 Norseway					tallation						Client	-	Read				
							dress	178a Hull,Road					Addres	First	Floor Offices				
		Stamford Bridge												12-18	12-18 Market Street				
		York Post Code: Y041 1DR						York						York					
										Post (Code: YC	010 3LF			I	Post Cor	de: YO1 8>	ks	
Gas Safe No:		182126 Telephone No: 07970555916					lephone N				 Telephone No:								
								Inspection Details											
Appliance Details					~ î	Τô		Inspec	ction Deta	ails	I			1					
	Locatio	on	Appliance Type	Make	Model	Combustion LOW (CO2% or CO/CO2 ratio)	Combustion HIGH (C02% or C0/C02 ratio)	Heat Input (KW) or Operating Pressure	CO Reading (ppm)	Appliance Inspected (YESNO/NAVIO) MU2 = Vaua Trappelon Only	FlueType (OF/RS/FL)	Landlords Appliance (YES/NO/NA)	Safety Device(s) Correct Operation (YES/NO/NA)	Ventilation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)	
1	Kitche	en	Combi boiler	Vaillant	28 VUW 286/3-3 VUW :	0.0000	0.0010	20 mb	93	YES	RS	YES	YES	YES	YES	NA	YES	YES	
2																			
3																			
4																<u> </u>			
																<u> </u>			
5 Faults/Notes							Remedial Work Taken									Warni	ng Notice	o Eixod	
1							nem	Wall										eTixeu	
2	2														-				
	3					_													
4																			
							_												
5								_	_										
Assessible: YES Clas rightness Satisfactory. YES								natures Gas ID Number: ort Issued By:									5675325		
Gas Installation Pipework Visual Inspection Satisfactory: YES Nam															Fri-26-07-2024				
Nur	mber of Appli	ances Te	sted: 1	Equipotential	Bonding: YES	1	port Received By:								-]			
NEXT INSPECTION DUE ON Sun-27-07-2025 Installation Pass: YES						ı	ame:	Signed:							Date:	Date: Fri-26-07-2024			
CO Alarm fitted & working? YES Smoke alarm fitted & working? YES								This Gas Safety Report was created by Gas Checker Software all rights reserved www.gaschecker.co.uk											

For appliances not owned by the Landlord the recorded 'Appliance Safe' response is based on a visual check for obvious defects only.