Landlord Home Owner Gas Safety Record





This inspection is for gas safety purposes only to comply with the Gas Safety (Installation and Use) Regulations. Flues have been inspected and checked for satisfactory evacuation of products of combustion. A detailed internal inspection of the flue integrity, construction and the lining has NOT been carried out.

Registered business				Job address	Job address			Landlord/agent			Certificate information		
Gas safe ID 552856 Reynolds Plumbing & Heating (RPH York Ltd) Unit 16, Rose Centre Rose Avenue Nether Poppleton York North Yorkshire Y026 6RX +44 01904345939				9 Maplehurst Avenue, York York North Yorkshire YO31 8JA			- John Coughlan 4A Moor Lane Copmanthorpe York YO23 3TH +44 07837847973			Date 07/10/2024 Number 1687 Next inspection due 07/10/2025			
No	Location	ocation Appliance type		Make/model		Flue type	Landlord appliance	s Appliance insp?	Combustion analyser reading	Operating press or heat input	ure Safety device correct ope	ce(s) ration	
1	Kitchen	Conventional/Regular/Heat-Only boiler		Valliant/Ecotec plus 415		RS	Yes	Yes	0.0007	19mbar	Yes		
2	Lounge	Gas fire		Verine portway/QUA16NV		OF	Yes	Yes	6.7KW		Yes		
No	Ventilation provi satisfactory	sion	Visual condition of termination satisfa		Flue performance checks	Appliar service	nce Ap	ppliance safe use	Approved CO alarm fitted?	Is CO alarm in date?	Testing of CO all satisfactory	larm	
1	Yes		Yes		N/A	Yes	Υe	S	Yes	Yes Yes			
2	Yes		Yes		Pass	No	Ye	S	Yes Yes Yes		Yes		
No	Defect(s) identified		Remedial act	Remedial action taken			g/Advice	Number of appliances tested 2					
								issued	Gas installation pipework (visual inspection) satisfactory?				
									Gas tightness test satisfactory?			Yes	
									Emergency control valve accessible?			Yes	
										ntial bonding satisfactory? Yes			
				lail	Production of the Control of the Con				Audible carbon monoxide alarm fitted?			Yes	
Engi Gas	neer information neer name: Colin Rey safe card ID: 570262 ature:			Name:	Received by: No person present			Comme	nts -				