

Domestic/Landlord Gas Safety Record

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out.

Certificate Reference

Steve Balding 6

Certificate No: G.M.2924

Engineers Details						Insta	Installation Details						Client Details						
Tra	ding Title	G M Plumbing And Heating					Installation						Client	Steve	e Balding				
Address		3 Norseway					dress	9 Monkgate Cloisters					Addre	SS 76 Ea	arswick Chase	9			
		Stamford Bridge					Monkgate					York							
		York						York											
		Post Code: Y041 1DR						Post Code: YO31 7HY					Post Code: YO32 9FY					9FY	
Gas Safe No:		182126 Telephone No: 07970555916					lephone N	io:				Telephone No:							
	ppliance De							Inspection Details											
		etano				≥ ĵ	Тĝ	D (a								0			
	Location		Appliance Type	Make	Model	Combustion LOW (C02% or CO/CO2 ratio)	Combustion HIGH (CO2% or CO/CO2 ratio)	Heat Input (KW) or Operating Pressure	CO Reading (ppm)	Appliance Inspected (YES/NO/NA/VIO) (V/D = V Burd Inspection Confy)	FlueType (OF/RS/FL)	Landlords Appliance (YES/NO/NA)	Safety Device(s) Correct Operation (YES/NO/NA)	Ventilation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)	
	Kitche	en	Central heating boi	ler Ideal	Ideal LOGIC HEAT 24		0.0008	18 mb	68	YES	RS	YES	YES	YES	NA	NA	YES	YES	
2																			
3															-				
4																			
5																			
Faults/Notes							Remedial Work Taken									Warning Notice Fixed			
1	1																		
2																			
3	+																		
4																			
5																			
Emergency Control Volvo								•											
Accessible: YES Gas rightness Satisfactory: YES								Signatures Gas ID Number: Report Issued By:									5675325		
Cap Installation Discusser's Visual Inspection Satisfactory								ne: G Murray Signed: C						Date:	Tue-24	09-2024			
Number of Appliances Tested: 1 Equipotential Bonding: YES								eport Received By:								L			
NEXT INSPECTION DUE ON Wed-24-09-2025 Installation Pass: YES						-	ame:	Signed:						Date:	Tue-24	09-2024			
	CO Alarm fitted & working? YES Smoke alarm fitted & working? YES							This Gas Safety Report was created by Gas Checker Software all rights reserved www.gaschecker.co.uk											

For appliances not owned by the Landlord the recorded 'Appliance Safe' response is based on a visual check for obvious defects only.