## LANDLORD/HOME OWNER GAS SAFETY RECORD

This inspection is for gas safety purposes only in accordance with the current edition of the Gas Safety (Installation and Use) Regulations. Flues were inspected visually and checked for satisfactory evacuation of products of combustion. A detailed internal inspection of the flue integrity, construction and lining has not been carried out.

**APPLIANCE DETAILS** 

Outcome of gas installation pipework visual inspection?

Outcome of gas supply pipework visual inspection?

Is the Emergency Control Valve access satisfactory?

Is the Protective Equipotential bonding satisfactory?

MAKE

LOCATION

KITCHEN

MODEL

GAS INSTA	ALLER: (Trading Title) D BUSSETT	1 SON LT	0
Name:	JAMES BUSSETT	Gas Safe Register No:	162777
Address:	1a HILBRA AVENUE	Gas Installer Ref. No :	N/A
	HAXBY , YORM	Date of Issue:	6/8/25
Post code:	Y032 3HF	Time of Issue:	N/A
	07718782846	Engineers Name: (print)	JAMES BLLSSETT

**FLUE TEST** 

Termination

Satisfactory

Yes/No

YES

Spillage Test

Pass/Fail

	TENANT/HOME OWNER DETAILS											
Tenant/Home (	Owner* Nam	e: MULTPL	E OCC	UPANCY								
Property Address: 10		DEVON	PLACE									
	Y	ORK			N. Committee							
Post Code	4010	3HD	Tel: N/A									
Tenant/Home (	Owner* prese	ent during inspection	1	YESMO								

SYSTEM

Flue Type

e.g. CF or RS

RS

	LA	NDLOR	D/AGENT DET	AILS (if applicable)	
Landlord/Ag	ent* Name:	me	DARREN	NORTH	i king
Address:	24	THE	AVENUE		
	HAXB	4 ,	YORK		
Post Code	Y032	3EC	Tel: O	7530897413	2000
Landlord/Age	ent* present	during insp	pection	YESMO	

Combustion

CO2 Ratio / CO2 CO

0.0011

PASS 1.28 ~3 HR

Performance Reading

Visual

Condition

Pass/Fail

PASS

KUJUJU	3,50	O KINO	COSMER	0	10/1	10.24	100	100	162	171-25	10 [10	10/11	10/1			100		. 03
								1										200
						i fage												
D	ETAILS (	OF ANY F	AULTS			REME	DIAL	ACTIC	N TAI	KEN		DE	TAILS	OF WOF	RK CARRIED	OUT	Delication of the Control of the Con	& WARNING E ISSUED
				1													Yes	NO
A.				2														
				3														
	100			4								1,24,413		C. C. KE				
				5											/			
The second secon				DETAILS OF ANY FAULTS	DETAILS OF ANY FAULTS  1 2 3 4													DETAILS OF ANY FAULTS  REMEDIAL ACTION TAKEN  DETAILS OF WORK CARRIED OUT  NOTICE

Yes/No

CO Alarm

tested

Pass/Fail

YES PASS N/A

Flue Flow

Test

Pass/Fail

**INSPECTION DETAILS** 

Adequate

Yes/No

Device

Correct

Operation

Operating Heat Input

18.6 27.11

Pressure

To re-order quote code 663010-NUM

Copies: White - Landlord/Agent/Home Owner

Outcome of gas tightness test?

Green - Registered Gas Installer

Pink - Tenant

Date:

Pass / Fail / NA

Pase / Fail / NA

Pass / Fail / NA

Pase / Fail / NA

Pass / Fail / NA

\* delete as applicable

This Safety Record is issued by Gas Installer: (SIGNED)

Received on behalf of Landlord / Home Owner: (SIGNED)

Two

Tenant/Landlord/Agent/Home Owner\*

Number of appliances tested:

1944096

ARCTIC HAYES

ATTENTION

Next safety

check due by:

6 /8 /25

RESULTS

Landlord's

Appliance.

Yes/No

YES

Appliance

Safe To Use

Yes/No

Inspected

Yes/No