

Landlord Gas Safety Record

Cert. No. 419

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure.

Company / Installer						Job Address							Customer / Landlord									
Engineer		Deklan Simpson				Name										Corrina						
Со	mpany	ny Simtec Plumbing And Heating S 27 Stray road York				Address	27	27							ny	MBE Limited						
Ad	dress						He	Heslington Road						Addres	S	villa farm wigginton road York						
							Yo	York														
																York						
						Post Code	YC	YO10 5AR														
Post Code Tel No. Gas Safe Reg ID Card No.		YO31 0NE 01904412109				Tel. No								Post Co		YO32 2RH						
														Tel. No								
		3 3916101																				
		3916101																				
Λ	ulianaa D	-1-11-							tion Dotoile				_									
Αр	pliance De	etalis	A college of Table	W.L.			EL . T		tion Details			un la con			Combonity	. 6.61 1. 1. 1. 1.	16. 19.19.	No. 1 Per	EL .	A college	I	
	Location	Appliance Type		Make	Mode	21	Flue Type	Appliance	Appliance inspected	Operating Pressure (mbar)	Heat Input (kW/h)	High Combus Reading Ratio CO				n Safety device(s) correct operation	Ventilation Provision satisfactory	Visual condition of flue and termination satisfactory	Flue Performance test	Appliance Serviced	Appliance safe to use	
1	Kitchen	١.	Boiler	Ideal	Logic + Co	ombi 24	NA	Yes	Yes	20.3	30	0.0011	-			_	Yes	Yes	Pass	Yes	Yes	
2	Kitcher	ı	Hob	Electra	Unkno		NA	Yes	Yes	NA	NA		-	_	NA N		Yes	NA	NA	NA	Yes	
3																						
4																						
5																						
6																						
Defects / Identified														L	abels ar	nd Warning N	lotice Issue	co Al	arm(s)			
	1														N/							
	2														N/	1		CO Ala	arm(s) fitte	d	Yes	
	3																	CO AL	arm(s) teste	v d		
	5																		atisfactory	:u	Pass	
	6																		·			
En	nergency Cor	ntrol Ac	cessible Yes Gas	Tightness Satisfactory Yes	s	Comr	nents															
Ga	s Installation	n Pipew	ork Visual Inspection																			
	Equipotonti	al Banc	ling Voc																			
Equipotential Bonding Yes																						
NE	XT INSPEC	TION D	UE BEFORE	09-Oct-2025																		
	gnatures																					
ISS	ued by:	Signe	d sall		Received S y:	Signed	d D						Dat	е	09-0	ct-2024						
			MIL	7	L	· , ·																
Pri	nt Name		Deklan Simpso	n	Р	rint Name																