

Landlord Gas Safety Record

Cert. No. 11434

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure.

Company / Installer						Job Address							Customer / Landlord						
Engineer	Anthony Stannard	Name	ι	Unknown					Name	Mrs Sara Esler									
Company	Nortons Heating				Address		4					Company Address							
Address Suite 4a Heritage House					Ν	Markham Street					The Barn								
	Dsbaldwick						York						Sand Hutton						
York												York							
					Post Code		YO31 8NR												
Post Code	t Code YO19 5UW			Tel. No	ι	Unknown						YO41 1LL							
Tel No.	01501111010											Tel. No	01904 468847						
Gas Safe Reg	Safe Reg 199682																		
ID Card No. 5424728																			
Appliance Details Inspection Details																			
Location	Appliance Type		Make	Mod	el	Flue Type	e Landlord's	Appliance Inspected	Operating Pressure	Heat Input (kW/h)			on Safety device(s)		Visual condition		Appliance	Appliance safe	
							Appliance		(mbar)		Reading Ratio CO	CO2 Ratio CO CC	correct operation	Provision satisfactory	of flue and termination	Performance test	Serviced	to use	
											ppm	% ppm %			satisfactory				
1 Bathroo	m .Boiler	r	Ideal	Logic Ma	ax C30	RS	Yes	Yes	18.6	30	.0010 105	9.9 NA NA N	A Yes	Yes	Yes	Pass	Yes	Yes	
2																			
3 4																			
5																			
6																			
									Lahels a	and Warning N	otice Issued				Creake				
Defects / Ide								Labels and Warning Notice Issued			CO Alarm(s			Smoke	Alarm(s)				
1										No									
2												CO Alarm(s) fi	tted	Yes	Smoke A	Alarm(s) fitt	ed	Yes	
3												CO Ala			Crusha	· · · · · · · · · · · · · · · · · · ·	4 - J		
5												CO Alarm(s) te and Satisfacto		Pass	and Sati	Alarm(s) tes sfactory	ted	Pass	
6													.,			oracio, j			
Emergency Co	ntrol Accessible Yes	Gas T	ightness Satisfactory Ye	s	Comr	nents													
Gas Installation Pipework Visual Inspection Satisfactory Yes																			
Gas installation	i Pipework visual ins	spections	dusiduory res																
Equipotential Bonding Yes																			
Water quality/l	evel of inhibitor acce	eptable	Yes																
NEXT INSPEC	TION DUE BEFORE		18-Jul-2025																
Signatures																			
Issued by:	Signed			ſ	Received S	Signed						Date	18-10	I-2024					
issued by:		him	~		y:	Signed						Dute	10-ju	1 2027					
	//	coron																	
Print Name	Anthon	ıy Stannaı	rd	Ĩ	Print Name		Antho	ony Stannard											