

Landlord Gas Safety Record

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure.

Company / Installer						Job Address							Customer / Landlord						
Engineer		Anthony Stannard	Name																
Company		Nortons Heating	Address	43					Company Address		Paul Blades								
Address		Suite 4a Heritage House				rth Ave	nue					43							
		Osbaldwick				York							Fourth Avenue						
		York			North Yorkshire								York						
			Post Code YO31 0UJ																
Post Code		YO19 5UW			Tel. No		nknown					YO31 0UJ							
Tel No.		01904411040										Tel. No							
Gas Safe Reg		199682																	
ID Card No.		5424728																	
10	nlianco D	otoile				ľ	nonor	tion Dotaile											
ΑÞ	pliance De Location	Appliance Type	Make	Mode	ol Eli	_		Appliance Inspected	Operating Processo	Heat Input (kW/b)	High Combusti	on Low Combustic	on Safety device() Ventilation	Visual condition	Flue	Appliance	Appliance safe	
	Location	Appliance Type	Маке	Mode		e type	Appliance	Appliance inspected	(mbar)	near input (kw/ii)	Reading	Reading	correct	Provision satisfactory	of flue and termination	Performance test	Serviced	to use	
											Ratio CO C ppm	CO2 % Ratio CO C ppm	02	Sutisfuctory	satisfactory	test			
1	Utility	Boiler	Worcester	Greensta	r 4000	RS	Yes	Yes	20.6	25	.0009 90 1	LO.O NA NA N	IA Yes	Yes	Yes	Pass	Yes	Yes	
2																			
3																			
4																			
5																			
6									Labala a								_		
De	fects / Ide	entified							Labels a	nd Warning No	otice Issued	CO Alarm(s	5)		Option	al Checks	5		
1										No		CO Alarm(s) f	itted	Yes	Smoke A	larm(s) fitt	ed	Yes	
	2																		
	3											CO Alarm(s) t and Satisfact		Pass	Smoke A and Sati	larm(s) tes	ted	Pass	
	4 5												ory			Slactory			
	6														Water q	uality/level	of inhibito	r Yes	
															accepta	ble		res	
_					Commo	ntc													
Em	nergency Cor	ntrol Accessible Yes	Gas Tightness Satisfactory Y	es	Comme	nts													
Gas Installation Pipework Visual Inspection Satisfactory Yes																			
Equipotential Bonding Yes																			
		-																	
NE	XT INSPEC	TION DUE BEFORE	04-Nov-2025																
Sic	natures																		
	ued by:	Signed	-	F	Received Sigr	ned						Date	29-(Oct-2024					
	,		um		by:								250						
		110																	
Pri	nt Name	Anthony S	Stannard	F	Print Name														