



Domestic/Landlord Gas Safety Record

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out.

Certificate Reference

Nick Cromer Street

Certificate No: G.M.2928

Engineers Details								Installation Details				Client Details								
Tradin	g Title	G M Plumbing And Heating						allation						Client	Nick I	Read				
Address		3 Norseway						Iress	9 Cromer Street				Address	14 WI	14 Whitelands					
		Stamford Bridge York Post Code: YO41 1DR							Clifton						York	York Earswick Chase				
									York					Earsv						
									Post Code:							Post Code: YO32			9FX	
Gas Safe No:		182126 Telephone No: 07970555916					Tel	ephone N):				Telephon							
Appl	iance De	etails							<u> </u>	Inspec	tion Deta	ails								
	Location		Appliance Type		Make	Model	Combustion LOW (CO2% or CO/CO2 ratio)	Combustion HIGH (CO2% or CO/CO2 ratio)	Heat Input (KW) or Operating Pressure	CO Reading (ppm)	Appliance Inspected (YES/NO/NA/VIO)	FlueType (OF/RS/FL)	Landlords Appliance (YES/NO/NA)	Safety Device(s) Correct Operation (YES/NO/NA)	Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)	
1 Ba	Bathroom Cupboard		Combi boiler		Vaillant	ecoFit Pure 830	0.0001	0.0005	18.5 mb	81	YES	RS	YES	YES	YES	YES	NA	YES	YES	
2																				
3																				
4																				
5																				
Faults/Notes							Remedial Work Taken									Warni	ng Notice	e Fixed		
1																		Warning House Fixed		
2																	+			
3																	+			
4																	+			
5																	+			
ш	ency Cont	rol Valve	- г		2 Table 0-1	Safa atau .	¬ Si	gnature	s											
Accessible: YES Gas rightness Satisfactory. YES								Report Issued By:									5675325			
Gas Installation Pipework Visual Inspection Satisfactory: YES YES								Name: G Murray Signed:						Date:	Tue-06-	08-2024				
Numbe	er of Appli	ances Te	sted:	1	Equipotential I	Bonding: YES	Re	Report Received By:												
NEXT I		ION DUE ON Wed-06-			6-08-2025 Installation Pass: YES		Na	me:			Signed:			Date		Date:	Tue-06-08-2024			
	ırm fitted a	& working	g? [YES Sr	noke alarm fitted &	& working? YES		Fo	This Gas Safety Report was created by Gas Checker Software all rights reserved www.gaschecker.co.uk For appliances not owned by the Landlord the recorded 'Appliance Safe' response is based on a visual check for obvious defects only.											