

Print Name

Paul Richardson

Print Name

P. Richardson

Landlord Gas Safety Record

Cert. No. 12795

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations 1998 section 26(9) and the Gas Industry Unsafe Situations Procedure.

Company / Installer						Job Address							Customer / Landlord							
Engineer	ngineer Paul Richardson					Name Unknown							Name							
Company	Nortons Heating				Address		40					Company	Paul Blades							
Address Suite 4a Heritage House						Newland Park Drive						Address	4							
Osbaldwick						,	York						Hill Garth							
	York												York							
					Post Cod	le ·	YO10 3HF	P												
Post Code YO19 5UW					Tel. No		Unknown					Post Code	YO41 5BP							
Tel No. 01904411040												Tel. No								
Gas Safe Reg 199682																				
ID Card No. 5424730																				
Appliance De								tion Details												
Location		Appliance Type	Make	Model		Flue Type	Landlord's Appliance	Appliance Inspected	Operating Pressure (mbar)	Heat Input (kW/h)	High Combustion Read	ling Low Combustion Reading	correct	Provision	Visual condition of flue and	Flue Performance	Appliance Serviced	Appliance safe to use		
											Ratio CO ppm CC	2 % Ratio CO CO	2 % operation	satisfactory	termination satisfactory	test				
1 Kitcher	n	Boiler	Worcester	Greenstar 21	LRi ErP	RS	Yes	Yes	18	21	0.0006 62.00 9.	67 0.0001 6.70 8	82 Yes	Yes	Yes	Pass	Yes	Yes		
2																				
3																				
4																				
5																				
6																				
Defects / Identified										Labels and Warning Notice Issued			m(s) Optional Checks							
1										No		CO Alarm(s) fi	ted	Yes	Smoke A	larm(s) fitt	ed	NA		
2										NO										
3													CO Alarm(s) tested			Smoke Alarm(s) tested				
4												and Satisfactory			and Satisfactory					
5													Water a	iality/level	of inhihitor					
6	6														acceptak		טו ווווווטונטו	Yes		
Emergency Control Accessible Yes Gas Tightness Satisfactory Yes Comments																				
Gas Installation Pipework Visual Inspection Satisfactory Yes Fire and smoke alarms are part of a full system as it's a student HMO and is controlled and tested by a third party																				
Equipotent	Equipotential Bonding Yes																			
NEXT INSPEC	TION D	OUE BEFORE	14-Jun-2026																	
Signatures								_												
Issued by:	Signe	d Tee	7		eceived	Signed			•			Date	11-Jui	n-2025						
		1/40	_	D	y:		1/2													