

Landlord Gas Safety Record

Cert. No. 12999

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations 1998 section 26(9) and the Gas Industry Unsafe Situations Procedure.

| Company / I | Job Address | | | | | | Customer / Landlord | | | | | | | | | | |
|--|--------------------------|----------------------------|------|---|-----------------------------|---------------------|------------------------------|-------------------|--------------------------|--------------------------------|-----------------------------|--------------|---------------------------------|-----------------------|----------------------------------|-----------------------|--|
| Engineer | Anthony Stannard | | | Name Unknown | | | | | | Name Mr Paul Blades | | | | | | | |
| Company | Nortons Heating | | | Address | 32a | | | | | Company | | | | | | | |
| Address | Suite 4a Heritage House | | | | Temple Avenue | | | | | Address | 4 | | | | | | |
| | Osbaldwick | | | | York | | | | | | Hill Garth | | | | | | |
| | York | | | | | | | | | | York | | | | | | |
| | | | | Post Code | YO10 3RT | | | | | | North Yorkshire | | | | | | |
| Post Code | ode YO19 5UW | | | Tel. No | Unknown | | | | | Post Code YO41 5BP | | | | | | | |
| Tel No. | No. 01904411040 | | | | | | | Tel. No | | | | | | | | | |
| Gas Safe Reg | 199682 | | | | | | | | | | | | | | | | |
| ID Card No. | 5424728 | | | | | | | | | | | | | | | | |
| | | | | | _ | | _ | | | | | | | | | | |
| Appliance D | etails | | | | Inspe | ction Details | 5 | | | | | | | | | | |
| Location | Appliance Type | Make | Mode | el Flue | ype Landlord's Appliance | Appliance Inspected | Operating Pressure (mbar) | Heat Input (kW/h) | High Combusti Reading | tion Low Combustion Reading | Safety device(s) correct | Provision | Visual condition of flue and | Flue Performance | Appliance Serviced | Appliance safe to use | |
| | | | | | " | | | | Ratio CO (| CO2 % Ratio CO CO2 | operation | satisfactory | termination satisfactory | test | | | |
| 1 Utility | Combi Boiler | Worcester | 34 C | ini Ri | 5 Yes | Yes | 18.6 | 34 | 0008 80 | 9.7 NA NA NA | | Yes | Yes | Pass | Yes | Yes | |
| 2 | Combi Boller | Worcester | 34 0 | | 163 | 103 | 10.0 | 34 | .0000 00 | 3.7 NA NA NA | 103 | 163 | 163 | 1 033 | 163 | 163 | |
| 3 | 3 | | | | | | | | | | | | | | | | |
| 4 | | | | | | | | | | | | | | | | | |
| 5 | | | | | | | | | | | | | | | | | |
| 6 | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | |
| Defects / Identified | | | | | | | | | | | | | | | | | |
| 1 | | | | | | | | No | | CO Alarm(s) fit | ted | Yes | Smoke A | Alarm(s) fit | ed | Yes | |
| | 2 | | | | | | | | | | CO Alarm(s) tested | | | Smoke Alarm(s) tested | | | |
| | 3 4 | | | | | | | | | and Satisfactory | | | | and Satisfactory | | | |
| 5 | | | | | | | | | | | • | | | • | | | |
| 6 | | | | | | | | | | | | | | | Water quality/level of inhibitor | | |
| | | | | | | | | | | | | accepta | acceptable | | | | |
| Emanual and Car | atual Assassible Vac | | | Commen | ts | | | | | | | | | | | | |
| Emergency Cor | ntrol Accessible Yes Gas | Tightness Satisfactory Yes | 5 | Commen | L | | | | | | | | | | | | |
| Gas Installation Pipework Visual Inspection Satisfactory Yes | | | | | | | | | | | | | | | | | |
| Equipotenti | al Bonding Yes | | | | | | | | | | | | | | | | |
| Equipotenti | al bollaling Tes | | | | | | | | | | | | | | | | |
| NEXT INSPEC | TION DUE BEFORE | 21-Aug-2026 | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | |
| Cional | | | | | | | | | | | | | | | | | |
| Signatures | Ciama d | | ь | Name to the state of the state | | | | | | D-t- | 70.4 | 2025 | | | | | |
| Issued by: | Signed | | | Received Signe by: | u | | | | | Date | 19-A | ug-2025 | | | | | |
| | m | w | · · | | | | | | | | | | | | | | |
| Print Name | Anthony Stanna | ard | Р | Print Name | | | | | | | | | | | | | |
| 22 | , and only ocume | | · | | | | | | | | | | | | | | |