



Domestic/Landlord Gas Safety Record

Certificate Reference

Nick2 12a Lilac Ave

Certificate No: G.M.21002

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out. This safety check complies with (but is not limited to) Regulation 26(9) of GSIUR.

Lingineers Details							moto	iiauoii L	Ctano					Ciletit De	, tano						
Trac	ding Title	G M Plumbing And Heating							allation Iress						Client	Nick I	Read				
Address		3 Norseway							ress	12a Lilac Avenue					Address	14 WI	14 Whitelands				
		Stamford Bridge								York						Earsv	Earswick Chase				
		York														York					
		Post Code: YO41 1DR								Post Code:							F	ost Cod	e: YO32	9FX	
Gas Safe No:		182126		Teleph	Telephone No: 079705		55016		ephone N	No:				– Telephor	e No:						
									J ' <u> </u>												
Ар	pliance De							I ∼ 6	Inspection Details								Г				
	Locatio	on	Appliance Type		Make		Model	Combustion LOW (CO2% or CO/CO2 ratio)	Combustion HIGH (CO2% or CO/CO2 ratio)	Heat Input (KW) or Operating Pressure	CO Reading (ppm)	Appliance Inspected (YES.NO.NA.VIO) (VD.= Veual Imperdor Only)	FlueType (OF/RS/FL)	Landlords Appliance (YES/NO/NA)	Safety Device(s) Correct Operation (YES/NO/NA)	Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)	
1	Kitche	Kitchen		Combi boiler		ınt	EcoTEC Plus 836	0.0000	0.0005	20 mb	39	YES	RS	YES	YES	YES	YES	NA	YES	YES	
2	2																				
3																					
Н	4																				
5																					
$oldsymbol{ol}}}}}}}}}}}}}}}}}}$	ults/Notos								Pom	odial Wa	rk Tako							Warnir	a Notic	o Fixed	
Faults/Notes 1									Remedial Work Taken									Warning Notice Fixed			
2																	1				
3																	<u> </u>				
4																	1				
5								_													
ш											_										
Emergency Control Valve Accessible: YES Gas Tightness Satisfactory: YES									Signatures Report Issued By: Gas ID Number:									5675325			
Gas Installation Pipework Visual Inspection Satisfactory:								1	N						·	Date:			Mon-25-08-2025		
Number of Appliances Tested: 1 Equipotential Bonding: YES								1	Report Received By:												
	T INSPECTION	ON DUE	DUE ON Tue-25-08-2026 Installati			on Pass: YES	•	me:		Signed:			Date:			Mon-25-08-2025					
CO	CO Alarm fitted & working? YES Smoke alarm fitted & working? YES]	_		This Gas Sa	afety Report wa	as created by	Gas Checker S	oftware all rights r	eserved wv	vw.gaschecker.co.i	uk			