



Domestic/Landlord Gas Safety Record Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations

Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out.

This safety check complies with (but is not limited to) Regulation 26(9) of GSIUR.

Certificate Reference

Nick 33 178a Hull,Road

Certificate No: G.M.21001

Engineers Details										Installation Details						Client D	etails					
Trading Title		G M Plumbing And Heating							Installation Address							Client		Nick Read				
Address		3 Norseway							Add	ress	178a Hull,Road					Addres	First I	First Floor Offices				
		Stamford Bridge															12-18	Market Stree	et			
		York								York						York						
		Post Code: YO41 1DR										Post Code: YO10 3LF			O10 3LF			Post Code: YO1 8XS				
Gas Safe No:		182126 Telep			ohone No: 079705		555916		Telephone N		o:				Telephone No:							
Appliance Details												Insped	ction Deta	ails								
	Location		Appliance Type		Make		Model		Combustion LOW (CO2% or CO/CO2 ratio) Combustion HIGH (CO2% or CO/CO2 ratio)		Heat Input (KW) or Operating Pressure	CO Reading (ppm)	Appliance Inspected (YES/NONA/VIO) (YOS - Vessa Inspector) Only)	FlueType (OF/RS/FL)	Landlords Appliance (YES/NO/NA)	Safety Device(s) Correct Operation (YES/NO/NA)	Ventilation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)	
1	Kitchen		Combi boiler		Vaillant		28 VUW 286/3-3 VU	w 0.	0000	0.0011	20 mb	105	YES	RS	YES	YES	YES	YES	NA	YES	YES	
2																						
3																						
4																						
5																						
Faults/Notes										Remedial Work Taken								I	Warning Notice Fixed			
1										Ì												
2																						
3																						
4																						
5																						
Emergency Control Valve Accessible: YES Gas Tightness Satisfactory: YES Sign																	Gas II	Number:	567532	5		
		Pipework	Visual Inspe	ection Satis	sfactory:		YES	3		_	ued By:			Signe	ed.	· Marine Carro		Date:	Mon of	-08-2025		
Numb	per of Applia	ances Te	sted:	1	Equipo	otential E	Bonding: YES	=		تا ت	Murray	Rv.		Oigite	<u>ح</u> ــــــــــــــــــــــــــــــــــــ	<u> </u>			IVIOI1-25	-00-2025		
NEXT INSPECTION DUE ON OR BEFORE: Fri-21-08-2026 Installation Pass: YES							=		port Received By: me: Signed: Date							Mon-25	-08-2025					
CO Alarm fitted & working? YES Smoke alarm fitted & working? YES										_		This Gas Sa	afety Report w	as created l	ov Gas Checker So	oftware all rights	reserved wy	ww.gaschecker.co	uk			