LANDLORD/HOMEOWNER GAS SAFETY RECORD



This record can be used to document the outcomes of the checks and tests required by The Gas Safety (Installation and Use) Regulations. Some of the outcomes are as a result of visual inspection only and are recorded where appropriate. Unless specifically recorded no detailed inspection of the flue lining, construction or integrity has been performed. Registered Business/engineer details can be checked at www.gassaferegister.co.uk or by calling 0800 408 5500

					,						
Details of Registered Business		Appliance Details									
Gas Safe Register No: 206115		Location of	Туре	Mai	nufacturer		Model		owned by ord/Homeowne	Inspect er Yes/N	
Registered Engineer's Name: 2-Paul Warriner	1	Kitchen	Hob	-	CDA	Н	G9320SS		Yes	Yes	
Gas Safe Register Licence No:	2	Boiler	Boiler	,	Vaillant	Ecot	ec plus 415		Yes	Yes	Rs
Business: N G Plumbing & Heating Ltd	3										
Address: 1 Lavender Way, Easingwold	4										
York					Inspection	<mark>on Details</mark>	<u>}</u>				1
Postcode: YO613GU		Operating pressure in mbar and/or heat	Operation of safety device(s)	Ventilation satisfactory	Visual Condition of flue and	Flue operation	Combustion analyser	Appliance Serviced	CO Alarm Fitted	CO Alarm tested (if	SAFE TO USE
Contact No: 01757 630633		input kW/h or Btu/h	. ,		termination	checks	reading			Fitted)	
Details of Site	1	18.64	Pass	Yes	N/A	N/A	0.0005	No	Yes	Yes	Yes
Name:							48ppm 9.0%				
Address: 9 Sails Dr 9 Sails Drive York YO10 3LR	2	18.67	Pass	Yes	Pass	Pass	0.0002 20ppm 9.1%	Yes	Yes	Yes	Yes
	3					<u> </u>				 	
	4							<u> </u>			
Details of Customer/Landlord	Safe	ety Related Def	ect(s) Identifie	d					GIUSP Classific	cation War	rning/Advisory Record nsert form serial No*
Name: Andy Cobley	1										
Address: Andy Cobley	3										
2a Sycamore Terrace	4										
York	Remedial Action Taken										
Postcode: YO30 7DN	1										
Contact No: +447971791271	2										
	3 4										
New Lord Application (Application)											
Number of Appliances tested: 2		ails of Work ca	rried out								
	Gas s	afety check									

Outcome of gas installation pipework visual inspection	Pass	Record Iss		
Outcome of gas supply pipework visual inspection	Pass	. 0		
Is the Emergency Control Valve access satisfactory?	Pass			
Outcome of gas tightness test?	Pass			
Is the protective Equipotential bonding satisfactory?	Pass	Date appli		

Record Issued by: p warriner

Received by name: andy

Date appliance(s)/flue(s) checked: 18/09/2025

Received by: Landlord

Attention

Next safety check due by: 18/09/2026