

## **Landlord Gas Safety Record**

Cert. No. 13154

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations 1998 section 26(9) and the Gas Industry Unsafe Situations Procedure.

Company / II	istaller	Job Address						customer / Landioru										
Engineer	Paul Richardson			Name Unknown						Name								
Company	Nortons Heating			Address 34							Paul Blades							
Address	Suite 4a Heritage House		Temple Avenue York					Address	4									
	Osbaldwick								Hill Garth									
	York		York						Elvington									
		Post Code YO10 3RT							York									
Post Code YO19 5UW			Tel. No						Post Code	YO41 5BP								
Tel No. 01904411040									Tel. No									
Gas Safe Reg 199682																		
	5424730																	
Appliance De	etails		_	_		ction Details	_		-									
Location	Appliance Type	Make	Model	Flue Type	pe Landlord's Appliance	Appliance Inspected	Operating Pressure (mbar)	Heat Input (kW/h)	High Combustion Reading Low Combusti Reading		Safety device(s correct	Ventilation Provision	Visual condition of flue and	Performance	Appliance Serviced	Appliance safe to use		
					''				Ratio CO ppm CC	2 % Ratio CO CO		satisfactory	termination satisfactory	test				
1 Kitchen	Boiler	Worcester	Greenstar 30i F	Erp Combi RS	Yes	Yes	18	30	0 0007 65 90 9	39 0 0001 4 50 8	59 Yes	Yes	Yes	Pass	Yes	Yes		
1 Kitchen Boiler Worcester Greenstar 30i Erp Combi RS Yes Yes 18 30 0.0007 65.90 9.39 0.0001 4.50 8.59 Yes Yes Yes Pass Yes   2														103				
3																		
4																		
5																		
6																		
Defects / Identified CO Alarm(s) Optional Checks																		
Defects / Identified																		
1					No				CO Alarm(s) fitted Yes			Smoke Alarm(s) fitted Yes						
2										CO Alarm(s) tested		Smoke Alarm(s) tested						
3 4										and Satisfactory				and Satisfactory				
5																		
6															Water quality/level of inhibitor Yes			
												acceptable						
Emergency Cor	ntrol Accessible Yes Gas	s Tightness Satisfactory Y	'ac	Comme	nts					-								
			es															
Gas Installation	Pipework Visual Inspection	n Satisfactory Yes																
Equipotenti	al Bonding No																	
		20 Can 2026																
NEXT INSPEC	TION DUE BEFORE	28-Sep-2026																
Signatures																		
Issued by:	Signed		F	Received Sign	ed					Date	26-50	p-2025						
	Signed //ee	1		oy:						2010	20 30	.p 2023						
Print Name	Paul Richardso	on	F	Print Name														