

Landlord Gas Safety Record

Cert. No. 12545

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations 1998 section 26(9) and the Gas Industry Unsafe Situations Procedure.

Company / I	Installer		Job Address							Customer / Landlord								
Engineer	neer Anthony Stannard				Name Unknown							Name	Mr Raul Pat	:el				
Company	Nortons Heating				Address	Flat 2	at 2					Company						
Address	Suite 4a Heritage House					24 Bar	bican Rd					Address						
	Osbaldwick					York												
	York					North `	Yorkshire	9										
					Post Code YO10 5AA							Post Code						
Post Code	Code YO19 5UW			Tel. No Unknown							Tel. No							
Tel No.	lo. 01904411040																	
Gas Safe Reg																		
ID Card No.	Card No. 5424728																	
Appliance Details Inspection Details																		
Appliance D		Analianaa Tura	. Flue					Heat Input (kW/h)	High Combust	i) Mantilation	Visual condition	Flue	Auglianas	Analianaa aafa		
Location	1	Appliance Type	Make	Mode	er riue	Type Land App	liance	iance inspected	Operating Pressure (mbar)	neat input (kw/n)	High Combust Reading Ratio CO ppm	Reading CO2 % Ratio CO (on Safety device(s correct operation	Ventilation Provision satisfactory	of flue and termination satisfactory	Flue Performance test	Appliance Serviced	Appliance safe to use
1 Kitchei	n	.Boiler	Veissmann	050) F	RS Y	es	Yes	20.5	25		9.1 NA NA I		Yes	Yes	Pass	No	Yes
2																		
3																		
4																		
5																		
6																		
Defects / Ide	entified			Labels and Warning Notice Issued					CO Alarm(s) Optional Checks									
1										No		CO Alarm(s)	fitted	Yes	Smoke	Alarm(s) fit	ted	Yes
2										140								
3												CO Alarm(s) tested				Smoke Alarm(s) tested Pass		
4												and Satisfact	cory		and Sat	isfactory		
5													Water o	Water quality/level of inhibitor Yes				
															иссери			
Emergency Co	ntrol Acce	ssible Yes Gas	Tightness Satisfactory NA		Comme	nts												
Gas Installation	n Pipeworl	< Visual Inspection	Satisfactory Yes		Inaccess	ible mete	er no dro	p test										
Equipotent	ial Bondin	g Yes																
NEXT INSPEC	TION DI	E DEEODE	28-Mar-2026															
NEXT INSPEC	TION DO	E BEFORE	20 1101 2020															
Signatures																		
Issued by:	Signed			R	Received Sign	ed						Date	28-N	1ar-2025				
		Min		b	y:													
Duint Name				5	wint Name													
Print Name		Anthony Stanna	ara	Р	rint Name													