

Säfe W.Duggan Plumbing & Heating

Landlord Gas Safety Record

Cert. No. 1286

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations 1998 section 26(9) and the Gas Industry Unsafe Situations Procedure.

NEXT INSPECTION DUE BEFORE	Emergency Control Accessible Yes Gas Installation Pipework Visual Ins Equipotential Bonding Yes	Defects / Identified 2 3 4 6	2 & 4 2 6	1 Hallway Cupboard	Location	Appliance Details	e Reg	Post Code YO8 5RU Tel No. 0774080	York Road North Duff	Address Park View		Company / Installer
Signed \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	spec	<u>a</u>		Boiler	Appliance Type		64	YO8 5RU 07740804161	York Road North Duffield, Selby	Park View	Wayne Duggan	4
	Gas Tightness Satisfactory Yes tion Satisfactory Yes 01-Nov-2026			Ideal	Make							
Received Signed by:				Icos He 15	Model			Tel.	Pos		Name	Job
	Boiler has b			72	Flue	Inspection Details		Tel. No	Post Code		Name Address	ob Address
	s been lea			RS Yes	Flue Type Landlor Appllan				York Yo10 5AS	Melbourne Court	Tenant	
	omments Boiler has been leaking internally and the drying up ;			Yes	Landlord's Appliance inspected Appliance			,	ω	ne Court		
	id the drying up			20.40	Operating Pressure (mbar)							
				15	Heat Input (kW/h)							
				0.0003 27 8	High Combus Reading Ratio CO							
Date		Laboration	-	8.7 NA NA NA				Post Code Tel. No		Address	Name Company	Customer / Landlord
		NA IC		A N A	Low Combustion Safety device(s) Reading correct Ratio CO CO2 operation ppm %			КОЛ	Hax	The	Mr T	r / Lanc
28-Oct-2025				Yes	ty device(s) correct peration			Y032 2QW	Moor Lane Haxby, York	The High Grange	Mr TJ & GR Allison	llord
t-2025		NA		Yes	Ventilation Provision satisfactory					nge	lison	
				Yes	Visual condition of flue and termination satisfactory							
		CO Alarm(s) fitted CO Alarm(s) tested and Satisfactory		Pass	Performance test							
		ie č		Yes	Appliance Serviced							
		Yes		Yes	Appliance safe to use							