BUS

Postcode YO41 1DZ	Telephone	Mobile	Engineer Name [illegible] Licence No

SITE

Tenant/Homeowner Name	
Address 95 Lawrence St	
Postcode YO10 4DZ	Contact No

CLIENT

Landlord/Agent Name G McMANAMAN	
Address 117 Fulford Road	
Postcode YO10 4BS	Contact No

APPLIANCES INSPECTED	1	2	3	4
DETAILS				
Location	Bathroom			
Owned by Landlord/Homeowner	(Yes) / No	Yes / No	Yes / No	Yes / No
Type	combi			
Manufacturer	IDEAL			
Model	LOGIC 30			
Serial No	[illegible]			
Chimney/Flue Type	RS			
INSPECTIONS & SAFETY CHECKS				
Inspected	(Yes) / No / Visual	Yes / No / Visual	Yes / No / Visual	Yes / No / Visual
Heat Input/Operating Pressure	29 (kW/Btu) mbar	kW/Btu mbar	kW/Btu mbar	kW/Btu mbar
Combustion Analyser Reading	0.0008 / N/A	N/A	N/A	N/A
Correct Safety Device(s) Operation	(Pass) / Fail	Pass / Fail	Pass / Fail	Pass / Fail
Satisfactory Ventilation	(Yes) / No	Yes / No	Yes / No	Yes / No
Visual Chimney/Flue and Termination Condition	(Pass) / Fail / N/A	Pass / Fail / N/A	Pass / Fail / N/A	Pass / Fail / N/A
Chimney/Flue Performance	(Pass) / Fail / N/A	Pass / Fail / N/A	Pass / Fail / N/A	Pass / Fail / N/A
Serviced	(Yes) / No	Yes / No	Yes / No	Yes / No
Safe To Use	(Yes) / No	Yes / No	Yes / No	Yes / No
DEFECTS & ACTIONS				
Safety Related Defects Identified and any Remedial Action Taken	ALL OK			
GIUSP Classification	(None) / AR / ID	None / AR / ID	None / AR / ID	None / AR / ID
Warning/Advisory Notice	Serial No:	Serial No:	Serial No:	Serial No:

OTHER WORKS

Number of Appliances Visually Checked

ALL O'K

CONCLUSIONS

Inspection of Visible Pipework	(Pass)	Fail	N/A
Tightness Test	(Pass)	Fail	N/A
ECV Accessible and Operational	(Pass)	Fail	N/A
Protective Equipotential Bonding	(Pass)	Fail	N/A
CO Alarm(s)	(Pass)	Fail	N/A
Smoke Detector(s)	(Pass)	Fail	N/A