



## Domestic/Landlord Gas Safety Record Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations

Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out.

This safety check complies with (but is not limited to) Regulation 26(9) of GSIUR.

Certificate Reference

Nicola 3 80 Crossways

Certificate No: G.M.2993

Engineers Details										Installation Details						Client D	etails				
Trading Title		G M Plumbing And Heating						Installation Address							Client	Nicola	<del></del> а				
Address		3 Norseway							Addi	ress	80 Crossways				Addres	24 Th	24 The Village				
		Stamford Bridge							Badger Hill						Wiggi	inton					
		York									York						York				
		Post Code: YO41 1DR									Post Code: YO10 5JF							ı	Post Coc	e: YO32	2PJ
Gas Safe No:		182126 Telepi			hone No: 079705559		55916		Telephone N		o:				Telephone No:						
A	opliance De	etails									Insped	ction Deta	ails								
	Locatio	Location		: Туре	Make		Model		Combustion LOW (CO2% or CO/CO2 ratio)	Combustion HIGH (CO2% or CO/CO2 ratio)	Heat Input (KW) or Operating Pressure	CO Reading (ppm)	Appliance Inspected (YES/NO/NA/VIO) (VIO = Vibual Improfort Only)	FlueType (OF/RS/FL)	Landlords Appliance (YES/NO/NA)	Safety Device(s) Correct Operation (YES/NO/NA)	Ventilation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)
1	Kitchen		Hob		Hotpoint		Na		null	null	19 mb	Na	YES	FL	YES	YES	YES	NA	NA	NA	YES
2	Loft		Central heating boiler		Worcester		Greenstar 15 RI	HE 0	0.0002	0.0006	17 mb	70	YES	RS	YES	YES	YES	YES	NA	YES	YES
3																					
4																					
5																					
Fa	ults/Notes	;		•			•	•	•	Reme	Remedial Work Taken							•	Warning Notice Fixed		
1																					
2	2																				
3	3																				
4																					
5																					
	Emergency Control Valve Accessible:  YES  Gas Tightness Satisfactory:  YES  Page 1																Gas IE	Number:	567532	5	
	Installation F	Pipework	Visual Inspe	 ection Sat	isfactory:		ΓY	ES			ued By:			Signe	od:			Date:	Th 07	00 0005	
Nun	nber of Applia	ances Te	sted:	2	Equipo	otential E	–	ES			Murray	n.		Oigile	,u	<b>Manufacture</b>	•		Tnu-07-	08-2025	
NEXT INSPECTION DUE ON OR BEFORE:  Mon-06-07-2026 Installation Pass: YES							=		eport Received By:  ame: Signed: Date:							Thu-07-	08-2025				
	CO Alarm fitted & working? YES Smoke alarm fitted & working? YES									This Gas Safety Report was created by Gas Checker Software all rights reserved, www.gaschecker.co.uk											