

Landlord Gas Safety Record

Cert. No. 12890

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations 1998 section 26(9) and the Gas Industry Unsafe Situations Procedure.

Cor	mpany / li	nstalle	er			Job Addr	ess						Customer / Landlord							
Engineer Company Address		Anthony Stannard Nortons Heating Suite 4a Heritage House Osbaldwick York				Name	Unknown						Name	Mrs Sara Esler						
						Address	4	4					Company Address							
							Ma	Markham Street						The Barn						
							Yo	York						Sand Hutton						
														York						
						Post Code	YC	YO31 8NR												
Post Code		YO19 5UW				Tel. No	Ur	Unknown					YO41 1LL							
Tel No.		01904411040					Tel													
Gas Safe Reg																				
ID Card No.		5424728																		
Appliance Details Inspection Details																				
Location				Make	Mode	el	F l ue Type	Landlord's Appliance	Appliance Inspected	Operating Pressure	Heat Input (kW/h)	High Combust	ion Low Combustion	Safety device(s)	Ventilation	Visual condition of flue and	Flue Performance	Appliance	Appliance safe to use	
								Appliance		(mbar)		Reading CO	Reading CO2 % Ratio CO CO	correct operation	Provision satisfactory	termination	test	Serviced	to use	
			D 11			620	D.C.			20.2	20	ppm	ppm 9	_		satisfactory				
1	Bathrooi	m	.Boiler	ldeal	Logic Ma	ax C30	RS	Yes	Yes	20.3	30	.0008 78	9.9 NA NA N	A Yes	Yes	Yes	Pass	Yes	Yes	
2																				
3																				
5																				
6																				
		. 1.01								Labola	and Warning No	otico Issuad	lloo al			lo "	1.01 1	_		
Dei	fects / Ide	entified								Labels and Warning Notice Issued			CO Alarm(s	Option	Optional Checks					
1 2								No			CO Alarm(s) fi	tted	Yes	Smoke Alarm(s) fitted						
3												CO Alarm(s) tested Pass and Satisfactory			Smoke Alarm(s) tested Pass and Satisfactory					
	4												and Satisfacto	чу		and Sati	Stactory			
-	5 6													Water g	uality/level	of inhibito	ır .			
	U															acceptable Yes				
Em	ergency Cor	ntrol Acc	cessible Yes Gas	Tightness Satisfactory Yes	5	Comn	ents													
Gas	s Installation	n Pinewo	ork Visual Inspection	Satisfactory Yes																
				Satisfactory Tes																
	Equipotenti	ial Bondi	ing Yes																	
NE	XT INSPEC	TION D	UE BEFORE	15-Jul-2026																
				,																
Sia	natures																			
İssı	ued by:	Signed	d		F	Received S	gned						Date	15-Ju	ıl-2025					
			Min	n		oy:														
Prir	nt Name		Anthony Stanna	ard	F	Print Name														