

Landlord Gas Safety Record

Cert. No. 11

HeatWorks with Liam

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations 1998 section 26(9) and the Gas Industry Unsafe Situations Procedure.

Company /	ompany / Installer					Job Address							Customer / Landlord							
Engineer	Liam I	Liam Batty			Name						Name	Mr Martyn I	nwood							
Company	HeatWorks with Liam			Address	19						Company	Watson Properties								
Address	49 Brecksfield York					Pi	Pinelands way						Stockton Lodge							
						Y	ork			Sandy Lane										
					Post Code								York							
						YO10 3QJ						Post Code								
Post Code Y030 1YE Tel No. 07903 313675 Gas Safe Reg 657315			Tel. No								YO32 9UT									
ID Card No.	65731	657315																		
Annlinna F) a ta ila							stian Dataile												
Appliance D		Appliance Type	Make	Mode	si .	Flue Type		tion Details		Heat Input (kW/h)	High Combustio	n Low Combustio	n Safety device(s	s) Ventilation	Visual condition	Flue	Appliance	Appliance cafe		
Location	"	Appliance Type	Make	Mode	:1	riue Type	Appliance	Appliance Inspected	(mbar)	neat input (kw/n)	High Combustio Reading	Reading	correct	Provision satisfactory	of flue and termination	Performance test	Appliance Serviced	Appliance safe to use		
											Ratio CO C	CO2 Ratio CO C % ppm	UZ	Satisfactory	satisfactory	test				
1 Loft		Boiler	ldeal	Logic 30kv	v Combi	RS	Yes	Yes	19	30	0.0016 145 8	.85 0.0003 28 8.	40 Yes	Yes	Yes	Pass	Yes	Yes		
2																				
3																				
4																				
5																				
6																				
Defects / Ide	entifie	ed										Labels a	nd Warning N	Notice Issue	co A	arm(s)				
1												N	4							
2															CO Ala	arm(s) fitte	t	Yes		
3 4															- CO AI	/ - \	. al			
5																arm(s) teste atisfactory	ea	Pass		
6																				
Emergency Co	ontrol Ad	ccessible Yes Gas	Tightness Satisfactory Ye	S	Com	ments														
Gas Installatio	n Pinaw	vork Visual Inspection																		
			Satisfactory Tes																	
Equipotent	tial Bon	ding Yes																		
NEXT INSPEC	CTION E	DUE BEFORE	17-Nov-2026																	
Signatures																				
Issued by:	Signe	ed /			Received	Signed		A				Date	17-N	lov-2025						
				1	by:															
Print Name Liam Batty Print Name Mr Martyn Inwood																				